

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-7

5a. Indicate Type of Lease

State ☐

Fed ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator William B. Yarborough	8. Farm or Lease Name L. E. Grizzell
3. Address of Operator 200 North Loraine - Suite 1400, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER B 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 8 TOWNSHIP 22-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat <del>Paddock</del> Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3435 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/4/88 - 10/12/88

Mix and pump 50 sx premium plus cement w/2 3/8" tbg. at 4900 ft. Pull tbg. to 4300 ft. and reverse clean. SI 15 hours - tagged plug at 4504. POOH

Ran bit and scraper, POOH, and ran RTTS to 3200 ft. and squeeze w/100 sx to 1000 PSI.

POOH and drill out cement - circulate to 3785 and test to 900 PSI.

Set CI bridge 3820, perforate 5 1/2" casing 3685 - 3504. Acidize w/1500 gal. 15% HCL acid swab. Acidize w/2000 gal. 20% HCL acid swab, good show of oil w/trace of water - testing

10/24/88

Shut in - observing surface pressures - and to continue testing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. J. Sexton TITLE Engineer

DATE 10-25-88

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

ZA Drinkard (Hald) E