## 1025 N. Fre h Dr.

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Hobbs, NM 88240

FORM APPROVED

	Bu	raget pri	reau No	. IU	M-0135
		Expires	_Marcl	31,	1993
5.	Lease	Designa	tion and	Ser	ial No.

LC-033706 (B) 6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals

7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well Val Well 8. Well Name and No. Other 2. Name of Operator C.P. Falby "B" #1
9. API Well No. Texaco Exploration & Production, Inc. 3. Address and Telephone No. 30-025-10103 P. O. Box 3109, Midland, TX 79702 (915) 688-4438 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Blinebry 11. County or Parish, State Unit Letter K, 1980 FSL, 1980 FWL Section 8, Township 22S, Range 37E Lea, New Mexico

12.	CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
	TYPE OF SUBMISSION	TYPE OF ACTION					
	Notice of Intent  Subsequent Report  Final Abandonment Notice	Abandonment  Recompletion  Plugging Back  Casing Repair  Altering Casing  Other	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off  Conversion to Injection  Dispose Water (Note: Report results of multiple completion on Well				
			Completion or Recompletion Report and Log form.)				

- 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- Set 4 1/2" CIBP @ 5375', Spot 25 Sx plug 5375'-5100' (Blinebry) WOC Tag
- Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL 2.
- Spot 40 Sx plug 3600'-3300' (7" shoe, Queen, Top-Liner) WOC Tag Spot 60 Sx plug 2700'-2400' (Yates, B-Salt) WOC Tag 3.
- Perf 6 holes @ 1400', Sqz 75 Sx plug 1400'-1200' (T-Salt) WOC Tag 5.
- Perf 6 holes @ 400', Sqz 100 Sx plug 400'-200' (10 3/4" shoe) WOC Tag
- 10 Sx Surface, Install dry hole marker. 7.

FROLEUM ENGINEER

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

4. I hereby certify that the foregoing is true and correct Signed	Title FACILITY ENGINEER	Date 9/24/01
Approved by	Title	Date
Conditions OFFICE SCIP.) DAVID R. GLASS		
Fide 18 U.S.C. Section 1001, makes it a crime for any person knoor representations as to any matter within its jurisdiction.	wingly and willfully to make to any department or agency of the Uni	ited States any false, fictitious or fraudulent stateme
DAVID R. GLASS	*See Instruction on Reverse Side	

5001 SEB 57 AM 8: 40

RECEIVED