P 8	CERTIFICA TO T	SAN TE OF CO RANSPOR	TOIL AND	1	FICE] 3 Well No. 3
Penrose-Skelly If well produces oil or condensate Unit Letter			Section	Fee Township	Range
give location of tanks			8	225	37E
Authorized transporter of oil 🔄 or condensate 📃			Address (give ac	ldress to which approved	copy of this form is to be sent)
Shell Pape Line Corp. P. O Box 1598, Hobod, New Mexaco					
Is Gas Actually Connected? Yes X No					
Authorized transporter of casing head gas 👝 or dry gas 🗌 Date Con- nected Address (give address to which approved copy of this form is to					copy of this form is to be sent)
Skeliy Oil Company			P. O. Box 1135, Eunice, New Minico		
If gas is not being sold, give reasons and also explain its present disposition: REASON(S) FOR FILING (please check proper box) New Well					
The undersigned certifies that the Rules and Regulations of the Oil Conservation Commission have been complied with.					
Executed this the <u>5th</u> day of <u>October</u> , 19 <u>64</u> . By					
OIL CONSERVATION COMMISSION				1116	S.B Deal
Approved by			Title Division Company	Poduction Sup 1 Company	
Date If the			Address P. O. Bo:	x 1858, Roswell	. New Mexaco 88201