

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name Grizzell "B"
3. Address of Operator P.O. BOX 68, HOBBS, NEW MEXICO 88240	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>8</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.	10. Field and Pool, or Wildcat Blinebry
15. Elevation (Show whether DF, RT, GR, etc.) 3427 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to perforate additional pay, reperforate old pay, acidize, and paraffin treatment.

MISU and POH with production equipment. RIH with perforating gun (3-1/8" hollow carrier gun). Perforate 5,412-16', 5,444-58', 5,464-70', 5,490-96', 5,504-21', 5,527-36' with 2 JSPF, 180 phasing. RIH with tubing and treating packer. Pump mixture of 5000 gallons Xylene and 200 gallons 15% HCl at 1-2 BPM. Set packer at 5,250'. Pump 5500 gallons 15% HCl max pressure 6000 psi. Flush with 35 bbl 2% KCl FW. POH with workover tubing and packer. RIH production equipment. Place well on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Stephen B. Braden

TITLE ADMINISTRATIVE ANALYST

DATE 9/14/86

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE AUG 19 1986

RECEIVED  
AUG 15 1986  
C.C.P.  
HOMES OFFICE