## NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
OTICE OF INTENTION O PLUG WELL	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
otice of Intention Squeeze	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
otice of Intention Gun Perforate	Notice of Intention (Other) String Shot	x	Notice of Intention (Other)	
IL CONSERVATION COMMISSION ANTA FE, NEW MEXICO	A Roswel	l, New 1	Mexico April	10, 1961
entlemen:				
Following is a Notice of Intention to	do certain work as described below  Grisse  tor)	at the	h	0
(Company or Opera	itor)		Well Noi	(Unit)
SW 1/4 SE 1/4 of Sec. 8	T. 265 , R )	,NMPM	, remose-overth	Po
Lea	County.			•
PROPOSED OPERATION	OW INSTRUCTIONS IN THE R		•	
		MO STET	19/1000 por rue puoce	over
open hole interval	3575' - 37001	_	10/1000 buting blow	over
open hole interval 2. Treat formation w/		_	isyloov buling show	over
open hole interval	3575' - 37001 1000 gallons 15% NE ac	_	dyloov buling show	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	syloot suling show	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	asyloot suling shows	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	Sylver Sulling Shows	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	isyloov suling shows	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	is the second se	over
open hole interval 2. Treat formation w/ 3. Recovered load.	3575' - 37001 1000 gallons 15% NE ac	_	isyloot suling shows	over
open hole interval  2. Treat formation w/  3. Recovered load.  4. Place on production  pproved	3575' - 37001 1000 gallons 15% NE ac	ld.	Oil Company	over
open hole interval  2. Treat formation w/  3. Recovered load.  4. Place on production	3575' - 37001 1000 gallons 15% NE ac:	Shell	Oil Company  Company or Operator Original	Signed By
open hole interval  2. Treat formation w/  3. Recovered load.  4. Place on production  pproved	3575' - 37001 1000 gallons 15% NE ac	Shell	Oil Company  Company or Operator Original	Signed B <b>y</b>

Box 1858, Roswell, New Mexico