Submit 3 Copies to Approviate District State of New Office E, gy, Minerals and						Resouces				FORM	C 102
DISTRICT [1625 N. French Dr., Hobbs, NM 3	88240									FORM Revised March 25	C-103 1999
DISTRICT II		OIL CONSERVATION DIVISION						WELL API NO.			
811 South First, Artesia, NM 882								30-025-10115			
DISTRICT III	117410		Sa	nta Fe,	NM 87505			5. Indicate Type of I		- 0	
1000 Rio Brazos Kd., Aztec, NM DISTRICT IV	07410							6. State Oil & Gas L	Ease No.	E FEE	
2040 South Pacheco, Santa Fe, N	M 87505										
S	UNDRY	NOTICES A	ND REPO	RTS ON	WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM					N OR PLUG BACK TO A C-101) FOR SUCH			7. Lease Name or Unit Agreement Name			
PROPOSALS.) 1. Type of Well:									G	rizzell	
OIL WE	LL	GAS WE	u 🗌	OTHER							
2. Name of Operator								8. Well No.		7	
Apache Corporation 3. Address of Operator	<u>]</u>							9. Pool name or Wil		7	
2000 Post Oak Blvc), Houston, '	Texas_7705	6-4400				Eunice; San		Southwest -	
4. Well Location Unit Letter	J :	2310	Feet From The	Sot	1thLine ar	ud 16	550	Feet From The	East	Line	
Section	8 1	ownship	228	Range	37E		NMPM	Lea	County		
			10. Elevation (Sh	ow whether l	OF, RKB, RT, GR,	etc.)					
			3410'	GR							
11. NO'	TICE OF IN	TENTION T		Appropria	ate Box to Indi	cate Nature o		Report, or Other SEQUENT RE		7:	
Perform Remedia	al Work	Plu	ug and Aband	on		Remed	lial Work		Alte	ring Casing	
Temporarily Aba	ndon	Па	nange Plans		Commence Drilling Operations 🗌 Plug and Abandonment						
Pull or Alter Casing											
					Casing Test and Cement Job						
Other						✓ Other		Plugback			
12. Describe propose of starting any pro or recompletion.											
9/ 19/00	MIRU.	Pull out of l	nole w/ proc	luction	equipment.	Run in h	ole w/ b	oit & scraper.	Pull out		
9/20/00	Run in h	iole w/ CIBI	P, set @ 53:	50' & to	p w/ 35' cer	ment. Pul	ll out of	hole.		$Z \neq 0$	V. ·
9/22/00	3807', 38	*	3844', 3852	2', 3856'	, 3870', 387	77', 3889',				ltes @ 3786', 3795 97', 4000', 4013', 4	
9/25/00	Acidize	San Andres	w/ 4500 ga	ıls 15%	HCL.						
9/26/00	Run in h	iole w/ prod	uction equi	pment &	z set @ 409	92'. Leave	e well cl	lamped & pre	ep to set l	arger puming unit.	
9/27/00	Set pum	ping unit. F	Return to pr	oductio.	n.						
I hereby certify that the heforn	nalite about is to	ue and counsister :	he beet of my know	ladge and be	lief						
SIGNATURE	obra			NON UE	TITI	F St	r Engin	eering Techr	vician	date 10/24/0	0

SIGNATURE	KORLING	<u>erven</u>	TITLE	Sr. Engineering Technicia	111 DATE	10/24/00	
TYPE OR PRINT NAM	e Debra J. Anderson	~			ELEPHONE NO.	713-296-6338	
(This space for State Us	e)	······································	Orig. Si Paul	gned by			
APPROVED BY		TITLE	Paul	Kautz	DATE	·	
CONDITIONS OF APP.	ROVAL, IF ANY:		Gen	logist			1

 \mathbb{A}_{r}