Sumi his notice in triplication to begin. A copy will be returne- sidered advisable, or the rejection be followed, and work should n	n by the Commission	n Commission or its y which will be given to a or agent, of the pla	proper agent before the avenue of the second	approved st
Regulations of the Commission.		notice by checking		
NOTICE OF INTENTION TO T	TEST CASING		INTENTION TO SHOOT CALLY TREAT WELL	OR
NOTICE OF INTENTION TO	CHANGE PLANS	NOTICE OF	INTENTION TO PULL WISE ALTER CASING	OR
NOTICE OF INTENTION TO I			WISE ALTER CASING	
NOTICE OF INTENTION TO		NOTICE OF	INTENTION TO PLUG	WELL
		dland, Texas	March 22, 1940)
of Sec. 9, T. 23-Si Les	County.			
Lee FUI	LL DETAILS OF COUNTY.	PROPOSED PLAN LES AND REGULAT	OF WORK MONS OF THE COMMISS	
Lee FUI	LL DETAILS OF COUNTY.	PROPOSED PLAN	OF WORK MONS OF THE COMMISS	
Lee FUI	LL DETAILS OF COUNTY.	PROPOSED PLAN LES AND REGULAT	OF WORK MONS OF THE COMMISS	
LOG FULOW INSTRUCT	LL DETAILS OF TOOLS IN THE RU	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH	OF WORK NONS OF THE COMMISS 3: NO.SACKS & MEKE	PLUG ON BOTTON 6:45 P.
FUI FOLLOW INSTRUCT ZE WEIGHT AMOUNT SET 24# 3618* E 111burton method used.	LL DETAILS OF T TIONS IN THE RU SET C. AT PORMATION 3629 Lime	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH OF WELL 3630'	I OF WORK NONS OF THE COMMISS 3: NO.SACKS & MAKE OF CEMENT 160 Sacks below & 250 Sacks above 2-stage tool El Toro Cement	PLUG ON BOTTON 6:45 P.
FUI FOLLOW INSTRUCT E VEIGHT AMOUNT SET 24# 3618* E Lliburton method used.	LL DETAILS OF T TIONS IN THE RU SET C. AT PORMATION 3629 Lime	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH OF WELL 3630'	I OF WORK NONS OF THE COMMISS 3: NO.SACKS & MAKE OF CEMENT 160 Sacks below & 250 Sacks above 2-stage tool El Toro Cement	PLUG ON BOTTON 6:45 P.
FUI FOLLOW INSTRUCT EXAMPLENT SET 24# 3618* EX Lliburton method used. Ll test with 1200# cold way	LL DETAILS OF T TIONS IN THE RU SET C. AT PORMATION 3629 Lime	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH OF WELL 3630'	I OF WORK NONS OF THE COMMISS 3: NO.SACKS & MAKE OF CEMENT 160 Sacks below & 250 Sacks above 2-stage tool El Toro Cement	PLUG ON BOTTON 6:45 P.
FUI FOLLOW INSTRUCT EXAMPLENT SET 24# 3618* EX Lliburton method used. Ll test with 1200# cold way	County. LL DETAILS OF FIONS IN THE RU SET C. AT FORMATION 3629 Lime tor pressure & 2 5 1940	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH OF WELL 3630' drill plug on M HUMBLE	I OF WORK NONS OF THE COMMISS 3: NO.SACKS & MAKE OF CEMENT 160 Sacks below & 250 Sacks above 2-stage tool El Toro Cement	HON PLUG ON BOTTOM 6:45 P. 3/21/40
FUI FOLLOW INSTRUCT EXAMPLEMENT SET 24# 3618 ¹ II Lliburton method used. Ll test with 1200# cold was MAR Approved	County. LL DETAILS OF FIONS IN THE RU SET C. AT FORMATION 3629 Lime tor pressure & 2 5 1940	PROPOSED PLAN LES AND REGULAT ASING AS FOLLOW TOTAL DEPTH OF WELL 3630' drill plug on M EUMBLE By	OF WORK NONS OF THE COMMISS 3: NO.SACKS & MAKE OF CEMENT 160 Sacks below & 250 Sacks above 2-stage tool El Toro Cement arch 23, 1940.	PLUG ON BOTTOM 6:45 P. 3/21/40

. . . and the second second

•••

▼ (

• t •