STATE OF NEW MEXICO

EN	ERGY AND MINERALS DE	PARTME	NT		
		•			
	DISTRIBUTION				
	SANTA FE				
	FILE				
	U.S.G.S.				
	LAND OFFICE		l		

Eddie W. Seay Oil & Gas Inspector

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-103

3.	ANTA FE			SANTA F	E, NEV	MEXICO 87501			Kevised 10-1-7	
•	148				•	,======================================		Sa. Indicate Ty	ne of Leave	
<u> </u>	.S.G.S.					•		State	Fee X	
ļ	AND OFFICE									
٥	PERATOR							5. State Oil & C	ias Lease No.	
	CI		VAIOTICE	S AND 5500	D.T.C. O.			mmm	mmm	
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE ""APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)										
1.				.,, = (, 0, 0, 0, 1	17 FOR 30	CH PROPOSALS.)		7. Unit Agreem	ent Name	
OIL]	OTHER-							
2. Name	of Operator							8. Farm or Leas	se Name	
Ex	xon Corporation	At	tn: Pei	mits Super	visor			J. L. Greenwood		
1 -	as of Operator			70700				9. Well No.		
L	O. Box 1600, M	ıdla	na, TX	79702					4	
4. Locat	ion of Well	_			_			10. Field cand F	-	
UMI	T LETTERL	•	905	EET FROM THE	South	LINE AND	FEET FROM	Pad	dock	
	Wost		0		225	270			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
THE	West LINE,	SECT10	N	TOWNSHIP		AANGE	НМРМ.			
m	mmm	\overline{m}	<i>(((((</i>			DF, RT, GR, etc.)			~}}}}}	
			///////////////////////////////////////		417' R			12. County Lea		
16.	<i></i>	7777	777777					L		
					licate N	lature of Notice, Repo				
	NOTICE)F IN	IENTION	10:		SUBS	EQUENT	REPORT OF	·•	
	M REMEDIAL WORK			PLUG AND ABA		REMEDIAL WORK	তি		RING CASING	
	ARILY ABANDON					COMMENCE DRILLING OPHS.	Ħ		AND ABANDONMENT	
_	ALTER CASINS			CHANGE PLANS		CASING TEST AND CEMENT JOS	. H	7200		
						OTHER		•		
OTHE	A				\Box					
<u>·</u>									· · · · · · · · · · · · · · · · · · ·	
17. Desc work	ribe Proposed or Comple 5 SEE RULE 1703.	led Op	erations (Cla	early state all per	inent det	ails, and give pertinent dates,	including	estimated date of	starting any proposed	
		•								
7.	B	1.								
1)	Repair hole in	n tb	g.		•					
2)	Acidize perfs	5150	o'∸5175'	w / 1300 ga	al of	15% HCL				
3)	Acidize perfs	5090	o'-5125'	w/ 1800 ga	al of	15% HCL				
	_									
4)	Acidize perfs	504:	550/5.	w/ 1550 ga	al OI	15% HCL				
						•			•	
10	-8-87 well pump:	ing :	11 BO, 7	3 BW, 14 K	ef ·					
					•			•		
	•									
18.1 here				and complete to	he best o	f my knowledge and belief.				
	∕⊅avid A.	MUI I	Lay							

RECEIVED

OCT 26 1987

OCO OCO OFFICE