

MISCELLANEOUS NOTICES

(Continued)

Pull tbg & pkr. Frac perfs 5504'-5523' & 5536'-5566' w/20000 gals Lse crude + 170 rubber ball sealers + 1/20# adomite + 1# sand per gal. Swab test Blinbry perfs. Kill Blinbry. Pull BP & pkr. Run 2" tbg to 6056' with seating nipple @ 5840', Guiberson KVL-30 pkr @ 5900' & Otis sliding side door @ 5870'. Complete Blinbry by swab thru 2" tbg w/sliding side door open. Close sliding side door & swab in Tubb.