NO. OF COPIES RECEIVED	00000 00000 0	Form C-103
DISTRIBUTION	HOBBS OFFICE O. C. C.	Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE	JUN 23 2 25 PM 18/	
U.S.C.S.		5a. Indicate Type of Lease
LAND OFFICE	4	State X Fee 5. State Oil & Gas Lease No.
OPERATOR	ــــــــــــــــــــــــــــــــــــــ	5. State Off & Sas Eedse No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO ORIGINAL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT _" (DO NOT PROPOSALS.)		
1.		7. Unit Agreement Name
OIL GAS WELL 2. Name of Operator	X OTHER- SWD	8. Farm or Lease Name
Mobil Oil Corporation		Brunson Argo
3. Address of Operator		9. Well No.
P. O. Box 633, Midland, Texas 79701		11
4. Location of Well		10. Field and Pool, or Wildcut
UNIT LETTER A	731 FEET FROM THE North LINE AND 589 FEET	FROM Penrose Skelly
	0 00 0 07 0	
THE LINE, SECT	TON 9 TOWNSHIP 22-S RANGE 37-E	MPM. ()
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
		Lea
PERFORM REMEDIAL WORK TEMPOPARILY ABANDON PULL OR ALTER CASING OTHER	PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS. CHANGE PLANS CASING TEST AND CEMENT JQB OTHER	ALTERING CASING PLUG AND ABANDONMENT
17. Describe Proposed or Completed C work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, inclu	uding estimated date of starting any proposed
4438, then ran Brown w/1000 gals 25% HCl a 1300, 5 min SIP 600, @3927, install wellhe Huskey pkr., ran plas	Well Serv. Unit, pulled cement lined the and property of the serve of	Serv. then treated perfs 2000, rate 4.8 BPM, ISIP tbg in derrick, reset pkr d & LD 2-3/8 tbg and BOT
set pkr @ 3954 w/10,0	1000# tension, install wellhead, return well to	prod. 6-19-67.
set pkr @ 3954 w/10,0	1000# tension, install wellhead, return well to	prod. 6-19-67.
set pkr @ 3954 w/10,0	000# tension, install wellhead, return well to	prod. 6-19-67.
s et pkr @ 3954 w/10,0	1000# tension, install wellhead, return well to	prod. 6-19-67.
set pkr @ 3954 w/10,0	000# tension, install wellhead, return well to	prod. 6-19-67.
set pkr @ 3954 w/10,0	000# tension, install wellhead, return well to	prod. 6-19-67.
	000# tension, install wellhead, return well to	prod. 6-19-67.
	000# tension, install wellhead, return well to	prod. 6-19-67.
	000# tension, install wellhead, return well to	prod. 6-19-67.
	000# tension, install wellhead, return well to	prod. 6-19-67.

DATE _

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY ___

Original Signed By John J. Hurt