BRUMSON ARGO #13, 6580 TD. SI 13 hrs, TP 640#, bled off pressure, swab 8 DNO + 61 BLW in ll hrs, L hr swb 3 bbls. S/O 92% LW, 100' FIH, sli sh -1057 BLW of gas, SI & SD. BRUNSON ARGO #13, 6580 TD SI 14 hrs, TP 7508, bled off pressure, swb 3 BNO + 20 BLW in 4 hrs, last hr swb 3 bbls., 100' FIH, sl sh of gas, rel pkr, tag sand fill-up @ 6040', P&LD 3-1/2" frac tbg, -1037 BLM changed rams in BOP, SD for nite. SD for weather. SI 37 hrs, CP 900#, kill well w/ 40 BSW, ran 3-1/2" SP, CO frac sanl, on BP @ 6055' ran ret tool on RTTS pkr & tbg to 6055', unseat BP, kill well w/ 90 BSW, ran BP to 6140', stopped, POH w/ tbg, pkr & BP, ran SP, CO frac sand 6140-6165', sand continuing to come in hole, SD for nite. BRUNSON ARGO #13, 6580 TD SI 13 hrs, CP 50#, bled off pressure, ran 3-1/2" SP, CO frac sand 6165-6195', ran 5-1/2" Baker Model R pkr on 2-3/8" tbg set @ 5848', from Tubb perfs swb 3 BNO + 64 BLW in 6 hrs, last hr swb 10 bbls. S/O, 97% LW, -1100 BLW 200' FIH, sl sh of gas, SD for nite. BRUNSON ARGO #13, 6580 TD SI 13 hrs, TP 1000#, bled off pressure, 3600' FIH, swb 2 BHO + 38 BLW in 10 hrs, last hr swb 2 bbls. S/O, 99% wtr, 150' FIH, sl sh of gas, SD for nite. -1062 BLW BRUNSOM ARGO #13, 6580 TD SI 13 hrs, TP 920#, bled off pressure, swb 1 BNO + 19 BLW in 8 hrs, last hr swb 2 bbls S/O, 98% wtr, 100' FIE, sl sh of gas, SI & SD. -1043 BLW BRUNSON ARGO #13, 6580 TD SD past 24 hrs for weather. BRUNSON ARGO #13, 6580 TD SI 49 hrs, TP 1200#, bled off press., swb 7 BLW w/ tr of oil 2 hrs, POH w/ tbg & pkr, ran Howco ret, BP & RTTS pkr, set BP @ 5865' & pkr @ 5633', Runco acidized Blinebry perfs 5656-5752' w/ 5000 gals 15% NE acid, used 30 RCNBS, DDTP 3500#, TTP 1100-4000%, AIR 2.8 BPM, ISIP zero, job comp. -180 BLW 0 5:00 p.m. 2-23-73, SI & SD. SI 13 hrs, TP zero, 2600' FIH, swb 103 BIM/ 11 hrs, last hr swb 6 bbls., sl sh of gas, 600' FIH, SI for 13 hrs, TP 480#, CP 800#, bled off press, swb 47 BLW + 2 BNO/ 11 hrs, 300' FIH, last hr swb 3 bbls., S/O 98% wtr, fr gas, CP 400#,

Sl & SD for nite.

-30 BLW

2