NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE OCC

Send Communications regarding well to:

Socony Mobil Oil Company, Inc. Box 1800, Hobbs, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

Notice of Intention Notice of Intention to Notice of Intention TO CHANGE PLANS TEMPORARILY ABANDON WELL TO DRILL DEEPER Notice of Intention Notice of Intention Notice of Intention X TO PLUG WELL TO PLUG BACK TO SET LINER Notice of Intention Notice of Intention Notice of Intention TO SQUEEZE TO ACIDIZE то Sноот (Nitro) X Notice of Intention NOTICE OF INTENTION Notice of Intention X TO GUN PERFORATE (OTHER) OIL CONSERVATION COMMISSION June 27, 1963 Hobbs, New Mexico SANTA FE, NEW MEXICO (Place) Gentlemen: Following is a Notice of Intention to do certain work as described below at the..... 13 Brunson Argo Socony Mobil Oil Company, Inc.Well No... (Company or Operator) 37 E ,NMPM., Drinkard 22 S .1/4 of Sec......Peol (40-acre Subdivision) Loa FULL DETAILS OF PROPOSED PLAN OF WORK (FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS) TD: 6580' PB: 6578' Cag: 13 3/8" @ 306 ₩/300 ax., 8 5/8" @ 3817 ₩/1000 ax., 5½" @ 6580 ₩/450 ax. Perfs: 6520-6573 Prepose to move in & rig up unit. Set CIBP @ 6200'. Dump 10' of Hydromite on top. Run GR collar leg. Perforate 52" cag. in Tubb zene @ apprex. 6110-6140 w/l JSFF. Run 22" tbg. w/full bore pkr. & set @ 6050'. Acidize Tubb zone w/500 gals. 15% NE Acid + Sand eil frac. w/20,000 gals crude + 20,000# 20-40# Ottawa sand + 1/40#/gal Addomite in 4 stages w/4 RCH ball sealers after each stage. Run Model D pkr. w/model B plug & set @ 6050'. Perforate Blimebry zone @ approx. 5490-5610' w/l JSFF. Rum 21 tbg. w/full bore pkr. & set @ 5400'. Acidise Blinebry perfs. w/1000 gals. 15% ME Acid + Sand oil frac w/40,000 gals crude + 40,000# 20-40# Ottawa sand + 1/40#/gal Addomite in 4 stages w/7 RCN Ball sealers after each stage. Run Tubb 2 1/16" tbg. to Except as follows: Position..

Address.....

Approved

Title.....

OIL CONSERVATION COMMISSION