

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-B1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. LC 061446
2. NAME OF OPERATOR SOHIO PETROLEUM COMPANY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 3000 Midland, Texas 79702		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1874' FNL & 766' FWL		8. FARM OR LEASE NAME Penrose
14. PERMIT NO.		9. WELL NO. 3
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3428' DF		10. FIELD AND POOL, OR WILDCAT Brunson (Ellenburger)
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec 9, T22S, R37E, NMPM
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

10. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) plug back

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

X

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

- 3-11-80: Set CIBP @ 8075', dmpd 2 sx cmt on top.
- 3-14-80: Perforated thru tbg 7378-82' 1 spf. Acidized with 600 gals acid. Swab tested lower zone (7378-82') no good.
- 3-18-80: Perforated 1 spf @ 7330-40'.
- 3-21-80: Acidized perms 7330-40' w/1500 gals 15% inhibited acid. Swab tested no recovery.
- 3-24-80: Set 7" WL BP @ 7322', dmpd 20' cmt on top.
- 3-25-80: Perforated upper zone 7230-60' 1 spf. No recovery with swab.
- 3-26-80: Acidized w/750 gals mud acid.
- 3-27-80: No recovery with swab.
- 3-28-80: Frac'd with 30,000 gals gelled wtr & 42,000# 20/40 sand. Swab tested.
- 4-17-80: Set pmpg unit, ran 1 1/4" pump.
- 4-18-80: Started pump testing. Waiting on test.

RECEIVED

APR 30 1980

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE District Superintendent

DATE 4-29-80

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED FOR RECORD

MAY 19 1980

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side