

NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator Gulf Oil Corporation 3. Address of Operator Box 670, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER H, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 10 TOWNSHIP 22-S RANGE 37-E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3384' GL	7. Unit Agreement Name South Penrose Skelly Unit 8. Farm or Lease Name 9. Well No. 167 10. Field and Pool, or Wildcat Penrose Skelly 12. County Lea
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Perforate & squeeze 6" casing and plug and abandon. <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Stop gas flow on the 6" - 9-5/8" annulus and P & A well as follows: Set CI BP at 3500', dump 35' cement plug on top of the CI BP, spot abandonment mud, spot 100' cement plug inside of 6" casing across the base of the salt section, perforate at 1300', attempt cement to the surface below retainer, run temperature survey if necessary, spot 50' surface plug, remove well head and install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>C. R. Kozekwa</u>	TITLE <u>Project Petroleum Engineer</u>	DATE <u>April 6, 1976</u>
APPROVED BY <u>[Signature]</u>	TITLE <u></u>	DATE <u>APR 7 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		

**RECEIVED**

APR 7 1976

OIL CONSERVATION COMM.  
HOBBS, N. M.