

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

3a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐
Name of Operator: **Chevron U.S.A. Inc.**
Address of Operator: **P.O. Box 670 Hobbs, NM 88240**
Location of Well: **UNIT LETTER H 1874 North 554**
East 10 22S 37E
THE LINE, SECTION TOWNSHIP RANGE NMPM.
15. Elevation (Show whether DF, RT, CR, etc.) **3375' GL**
10. Field and Pool, or Wildcat **Eunice San Andres South**
12. County **Lea**

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

INFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
ILL OR ALTER CASING ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

OTHER ☒ Add perforations

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPER. ☐

CASING TEST AND CEMENT JOB ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

Abandon old San Andres perforations and add new San Andres perforations. Set CIBP @ 4000'. (Top of old perforations @ 4018'.) Test CIBP and casing to 500 psi for 30 minutes. Add perforations from 3836' - 3952'. Acidize as necessary. Equip to pump. Return to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

by P. H. Bailey Jr.

TITLE Division Drilling Manager DATE 7-23-1986

ORIGINAL SIGNED BY JEFFERY SUTHERLAND

OVER BY DISCOUNT SUPERVISOR

TITLE _____

DATE JUL 25 1986

CONDITIONS OF APPROVAL, IF ANY: _____

RECEIVED
JUL 24 1986
G.S.P.
Housing Office