

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-10174
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.
Lease Name or Unit Agreement Name BRUNSON-ARGO
Well No. 6
Pool name or Wildcat BLINEBRY/DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
Name of Operator TITAN RESOURCES I, INC.	
Address of Operator 500 WEST TEXAS, SUITE 500, MIDLAND, TEXAS 79701	
Well Location Unit Letter <u>E</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>WEST</u> Line Section <u>10</u> Township <u>22S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3419GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: FRACTURE BLINEBRY ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POOH W/RODS AND PUMP. ND WELLHEAD, NU BOP. POOH W/TBG.
RIH W/RBP, PKR, & TBG. SET RBP @ 6000'. TEST RBP TO 3000 PSI. POOH W/TBG. & PKR.
RIH W/5" X 2 3/8" TREATING PKR W/ON-OFF TOOL AND 2 3/8" PROFILE NIPPLE ON 3 1/2" FLUSH JOINT FRAC TBG. TEST TBG.
TO 8000 PSI. SET PKR. @ 5000'. LOAD ANNULUS W/2% KCL WTR & PRESS. TO 500 PSI. FRAC PER FRAC RECOMMENDATION.
FLOW WELL BACK.
SET BLANKING PLUG IN PROFILE NIPPLE, RELEASE ON/OFF TOOL, POOH & LD FRAC TBG.
RIH W/PROD. TBG. & ON/OFF TOOL. IATCH ON PKR. pULL BLANKING PLUG. SWAB, IF NECESSARY.
PLACE WELL BACK ON PRODUCTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Brenda Coffman TITLE REGULATORY ANALYST DATE 12-09-97

TYPE OR PRINT NAME BRENDA COFFMAN TELEPHONE NO. (915) 498-8662

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 05 1998