

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-10174

Indicate Type of Lease

STATE ☐

FEE ☒

State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

Name of Operator
TITAN RESOURCES I, INC.

Lease Name or Unit Agreement Name
BRUNSON-ARGO

Well No.
6

Address of Operator
500 WEST TEXAS, SUITE 500 - MIDLAND, TEXAS 79701

Pool name or Wildcat
BLINEBRY/DRINKARD

Well Location

Unit Letter E : 1980 Feet From The NORTH Line and 660 Feet From The WEST Line

10 Section 22S Township 37E Range NMPM LEA County

Elevation (Show whether DF, RKB, RT, GR, etc.)
3419 GR.

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Clean out, acidize and put on pump ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Blinebry/Drinkard downhole commingled - DHC - 8929

6-13-97 MIRU pulling unit. POOH with tubing. RIH with clean out bailer. Cleaned out to 6535'. Blinebry perms: 5442' to 5834'; Drinkard perms: 6307' to 6494'.

6-14-97 RIH with packer on tubing. Set packer at 6256'. Swabbed dry in 5 runs. Acidized perms 6307' - 6494' with 2,000 gals 15% NeFe HCL. RU swab. Swabbed back 15 bbls load water.

6-15-97 Swabbed back 3 BO, 62 BLW.

6-17-97 Swabbed 22 bbls fluid, 20% oil. POOH with packer. RIH with retrievable bridge plug and packer. Set RBP at 5890', set packer at 5380'. Swabbed well dry.


6-18-97 Acidized perms 5442' - 5834' with 3,000 gals 15% NeFe HCL. RU swab, recovered 22 bbls load water.

6-19-97 Swabbed well dly. Released packer, retrieved RBP and POOH. RIH with production tubing, set at 6532', SN at 6498'.

6-20-97 RIH with pump and rods and put on production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE PRODUCITON OPERATIONS MANAGER

DATE 06-20-97

TYPE OR PRINT NAME BRUCE WOODARD

TELEPHONE NO. 915/682-6612

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 27 1997