-+-	-				
1	Submit 3 Copies 10 Appropriate District Office	State of New N Energy, winerals and Natural 1			Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240		OIL CONSERVATION DIVISION 2040 Pacheco St.			
				WELL API NO. 30-025-10175	
	DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	87505	5. Indicate Type of Lease	
I	DISTRICT III				
1	000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease ! -	No.
	SUNDRY NOTICES AND REPORTS ON WELLS				
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1.	. Type of Well:			Brunson-Argo	
	OE GAS WELL	OTHER			
2	Name of Operator			8. Well No.	
3.	Titan Resources I, Inc. Address of Operator			14	
	500 W. Texas, Suite 500, Midland, Texas 79701			9. Pool name or Wildcat Paddock	
4.	Well Location				
	Unit Letter:	Feet From The North	Line and1980	Feet From The	West Line
	Section 10	Township 22S R	ange 37E	MMPM Lea	County
		10. Elevation (Show whether		V////	
3414' GR					
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING					
PULL OR ALTER CASING CASING TEST AND CE					
OTHER: OTHER: OTHER:Complete Addit:					
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
5/14/97 MIRU pulling unit. POOH with rods, pump and tubing. RIH with bit and clean-out bailer					
	on tubing. Tagge	d IIII at 5190°. (Per	ts: 5029' to 518	8'). Cleaned out	to 5190' POOH
	D/9/ RIH & Clean out to	o 5208'. SD for rig r	cepairs.		
5/16/97 SD for rig repairs.					
5/1	/17/97 POOH with tubing, bailer & bit. /18/97 RIH with packer and tubing. Set packer at 4967'. BU swab and swabbed well down				
	18/97 RIH with packer and tubing. Set packer at 4967'. RU swab and swabbed well down. 20/97 Acidized with 3000 gals 15% HCL + chemicals. RU swab and swabbed back load.				
5/2	21/97 POOH with tubing and packer. Perforated Upper Paddock from 5012' to 5028' (17 shots)				
	RIH with retrievable bridge plug & packer. Set RBP at 5030'. Set packer at 4969'				
	Acidized perfs 5012' to 5029' with 1200 gals 15% HCL + chemicals. Released packer, retrieved bridge plug and POOH. RIH with 167 jts 2 3/8" tubing for production. Seating				
	nipple at 5156'.	jing and room. Kin wi	$107 \text{ Jts } 2 3/8^{\circ}$	tubing for proc	luction. Seating
5/22/97 RU swab, Recovered 53 bbls load water, 10% oil cut					
5/23/97 TP 550 psi. /Weil Kicked off flowing. Returned well to production.					
Ihe	reby certify the the information above is true at				
SIC	NATURE	Pr m	oduction Operatio	-	6/2/97
TYP	EOR FRINT NAME Bruce Woodard	•	HO		5)498-8663
		NED BY CHRIS WILLIAMS			
(10)	s space for State Use) ORIGINAL SIG DISTR	ICT I SUPERVISOR		\bigcirc	HILL A A JOOT
APP	ROYED BY		-	A	JUN 09 1997
	DITIONS OF AFFROVAL, IF ANY:	······································		DATE	