

BRUNSON ARGO #16, 7454 TD, 5256 PBTD
 1/4 F 16 BNO + 22 BLW + 369 MCFG/ 24 hrs
 30/64" ck, TP 80#. -1054 BLW

BRUNSON ARGO #16, 7454 TD, 5256 PBTD
 1/5 F 11 BNO + 21 BLW + 318 MCFG/ 24 hrs
 30/64" ck, TP 80#. -1033 BLW

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/8 F 33 BNO + 68 BLW + 987 MCFG/3 days, 30/64 ck, TP 75. - 965 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/9 F 10 BNO + 24 BLW + 338 MCFG/24 hrs, 30/64 ck, TP 80. - 941 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/10 No rpt.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/11 No rpt.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/12 No rpt.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/15 No rpt.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/15 F 44 BNO + 127 BLW + 317 MCFGPD/6 days, 30/64 ck, TP 80. - 814 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/16 F 4 BNO + 26 BLW + 333 MCFG/24 hrs, 30/64 ck, TP 80. - 788 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/17 F 0 BO + 54 BLW + 337 MCFG/24 hrs, 30/64 ck, TP 80. - 734 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/18 F 5 BNO + 22 BLW + 328 MCF/24 hrs, 30/64 ck, TP 80. - 712 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/19 F 8 BNO + 36 BLW + 337 MCFG/24 hrs, 30/64 ck, TP 80. - 686 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/22 F 19 BNO + 91 BLW/3 days, 30/64 ck, TP 80. - 595 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/23 F 4 BNO + 25 BLW/24 hrs, 30/64 ck, TP 80. - 570 BLW.

BRUNSON-ARGO #16, 7454 TD, 5256 PBTD.
 1/24 Correction to 1/23/71 rpt: Should be "F" - not: "P".
 F 6 BNO + 20 BLW/24 hrs, 30/64 ck, TP 70. - 550 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/25 F 0 BNO + 10 BLW/24 hrs, 30/64 ck, TP 70. - 540 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/26 F 7 BNO + 20 BLW/24 hrs, 30/64 ck, TP 70. - 520 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/29 F 22 BNO + 51 BLW/72 hrs, 30/64 ck, TP 70. - 469 BLW.

BRUNSON ARGO #16, 7454 TD, 5256 PBTD.
 1/30 F 5 BNO + 16 BLW/24 hrs, 30/64 ck, TP 70. - 453 BLW.