

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, 87505

WELL API NO.

30-025-10180

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☒

GAS  
WELL ☐

OTHER

2. Name of Operator

Titan Resources I, Inc.

3. Address of Operator

500 W. Texas, Suite 500, Midland, Texas 79701

4. Well Location

Unit Letter E : 1980 Feet From The North Line and 760 Feet From The West Line

Section 10 Township 22-S Range 37-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3433 RKB

7. Lease Name or Unit Agreement Name

Brunson-Argo

8. Well No.

19

9. Pool name or Wildcat

Paddock

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☒

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Complete Additional Pay in Paddock ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-2-97 MIRU pulling unit. POOH with rods, pump, and tubing. RIH with clean-out bailer and bit. Tagged fill at 5103'. (Perfs: 5088'- 5202') Cleaned out to 5118'. POOH. Bit indicated drilling on metal.

5-3-97 RIH with fishing tools. Could not catch fish. Ran different fishing tools. Could not catch fish.

5-4-97 Changed fishing tools. Caught fish but could not pull.

5-6-97 RIH with washover shoe and washpipe. Milled to 5150'. POOH. Shoe worn out.

5-7-97 RIH with fishing tools. Caught fish and pulled. Recovered retrievable bridge plug. RIH with clean-out bailer and bit.

5-8-97 Cleaned out to 5206'. POOH. RIH with packer and tubing. Set packer at 5040'. Acidized perfs 5088' to 5202' with 1,500 gals 15% NeFe HCl + 1,500 gals chemical. RU swab and swabbed back 52 bbls load water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Production Operations Manager

DATE 5/16/97

TYPE OR PRINT NAME

Bruce Woodard

(915)682-6612  
TELEPHONE NO.

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 21 1997