DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	NEW MEXICO OIL CONSERVATION COM	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State Fee X S. State Oil & Gas Lease No.
	NOTICES AND REPORTS ON VELLS	
(DO NOT USE THIS FORM FOR FROP) USE "APPLICATIO	INCHICE AND INCTION 13 ON WELLS OSALS TO OPILL ON TO DEFEN OR PLUS BACK TO A DIFFERENT H FOR PERMIT - " (FCFM C-101) FCR SUCH PROPOSALS.)	7, Unit Agreement Name
1. OIL X GAS WELL X	OTHER-	
2. Name of Operator		8, Farm or Lease Name
John H. Hendrix 3. Address of Operator		S. E. Long 9. Well No.
	, Midland, Texas 79701	#2
4. Location of Well	980 FEET FROM THE South LINE AND	
	11 TOWNSHIP 22-S RANGE	
millioninini	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3351' DF	Lea
Check A	ppropriate Box To Indicate Nature of Notic	ce, Report or Other Data subsequent report of:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER Perforate addit	PLUS AND ABANDON REMEDIAL WORK COMMENCE DEILLI CABING TEST AND OTHER	-
17. Describe Proposed or Completed Ope work) SEE RULE 1703.	rations (Clearly state all pertinens details, and give perti	inent dates, including estimated date of starting any proposed
work, but hour hour		
Proposed work to com	mence 10-15-73	
Proposed work to com		
1. Rig up service u	unit and pull tubing and packer.	
l. Rig up service u		nd 6262'.
 Rig up service u Perforate with 1 Run 3 1/2" frac 	unit and pull tubing and packer.	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo Pull 3 1/2" tubir 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo Pull 3 1/2" tubir 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo Pull 3 1/2" tubir 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	
 Rig up service u Perforate with 1 Run 3 1/2" frac and 70,000 gallo Pull 3 1/2" tubir 	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	
1. Rig up service u 2. Perforate with 1 3. Run 3 1/2" frac and 70,000 gallo 4. Pull 3 1/2" tubin 5. Test well.	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude. 1 and pull tubing and packer.	5206'-6475' with 70,000# sand
1. Rig up service u 2. Perforate with 1 3. Run 3 1/2" frac and 70,000 gallo 4. Pull 3 1/2" tubin 5. Test well.	unit and pull tubing and packer. 1 3/8" jet @ 6206', 6227', 6249' and tubing and fracture perforations 6 ons gelled lease crude.	5206'-6475' with 70,000# sand