

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.D.I.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☐	For ☒
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		7. Unit Agreement Name
2. Name of Operator Exxon Corporation		8. Farm or Lease Name Paddock Unit
3. Address of Operator P. O. Box 1600, Midland, TX 79702		9. Well No. 70
4. Location of Well UNIT LETTER <u>H</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>11</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.		10. Field and Pool, or Wildcat Paddock
15. Elevation (Show whether DF, RT, GR, etc.) 3355 DF		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pulled rods and tubing.
2. Set CIBP at 4950' w/10 sx plug on top.
3. Spot 20 sx plug at 2800' and 20 sx plug at 3300'.
4. Cut 5 1/2" csg at 2785' and pulled.
5. Spot 35 sx plug at 2850' top of cmt 2700'.
6. Spot 70 sx plug at 1200', 35 sx plug at 355', and 10 sx plug at surface.
7. Install dry hole marker as required by NMOCC.
FRW 9-12-79.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED C. J. Jack TITLE Unit Head DATE 12-5-79

APPROVED BY E. J. [Signature] (AAP) TITLE OIL & GAS INSPECTOR DATE AUG 10 1983
CONDITIONS OF APPROVAL, IF ANY: