

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-10213
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Lou Worthan
8. Well No. 11
9. Pool name or Wildcat Blinebry Oil & Gas

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Marathon Oil Company

3. Address of Operator  
PO Box 2490 Hobbs, NM 88240

4. Well Location

Unit Letter G : 1980 feet from the North line and 1980 feet from the East line

Section 11 Township 22-S Range 37-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
GL 3341' KB 3354'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Lower tubing in Blinebry ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1/5 RU wireline. Set blanking plug in profile nipple at 4748'. RD wireline.

1/7 RU pulling unit. ND wellhead. NU BOP. Release on/off tool. Circ hole. Rel pkr at 4738', POOH.

RIH w/2 3/8" production string. ND BOP. Set tbg anchor at 4674'. NU wellhead. Open well to flowline.

1/10 RD pulling unit.

RECEIVED  
Hobbs  
OC0

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kerry Cook TITLE Admin. Assistant DATE January 14, 2003

Type or print name Telephone No.

(This space for State use) ORIGINAL SIGNED BY

GARY W. WINK

APPROVED BY GARY W. WINK TITLE Manager DATE JAN 16 2003

Conditions of approval, if any: