

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-10213</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Lou Worthan</b>
8. Well No. <b>4</b>
9. Pool name or Wildcat <b>Blinebry Oil &amp; Gas</b>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator <b>Marathon Oil Company</b>	
3. Address of Operator <b>P.O. Box 2490 Hobbs, NM 88240</b>	
4. Well Location Unit Letter <b>G</b> : <b>1980</b> Feet From The <b>North</b> Line and <b>1980</b> Feet From The <b>East</b> Line Section <b>11</b> Township <b>22-S</b> Range <b>37-E</b> NMPM <b>Lea</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>GL 3341 KB 3354</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Reactivate Well & Perf in Blinebry** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8/5 MIRU PU. ND wellhead. NU BOPE. POOH w/2 3/8" tbg. Rel RBP at 3570'. POOH. RIH w/pkr, test CIBP at 5000'. 8/6 Cmt sqz perfs at 3632-3722 w/150 sxs cmt. DO cmt, CIBP and drld 4 3/4" hole to 6205'. Open hole from 4 3/4 to 6 1/2 from 5146-6205'. 8/19 RIH w/4" liner to 6204'. Cmt w/166 sxs cmt. TIH. DO 4749-4771'. Test liner, csg & sqzd perfs to 1000 psi. OK. RIH. DO cmt in liner. Clean out to 6165'. Pickle tbg w/700 gals 15% acid. Spot 100 gals 15% acid across 5600-5750'. 8/23 Perf 5648-54', 5664-80', 5700-10', 5722-50', w/4 SPF, 90 deg phas. RIH w/pkr, set at 5569'. Acidize w/2000 gals 15% acid w/100 BS. Swab well. Open to test tank. 8/25 Rel pkr at 5569', POOH. RIH w/3.12" CIBP, set at 6165'. Test to 8500 psi. OK. 8/26 Frac 5648-5750' w/71,000 gals Delta Frac 25 carrying 201,000 lbs 20/40 sand. TIH w/pkr, set at 4753'. Flow back, RU testers. 8/28 Set plug in on/off tool. Displace csg w/pkr fluid. ND BOPE. NU wellhead. 8/29 Swab. Ret plug in on/off tool. RD PU.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 9/1/98  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY CHRIS WILLIAMS TITLE DISTRICT I SUPERVISOR DATE 9/1/98  
CONDITIONS OF APPROVAL, IF ANY: