

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-10214</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Lou Worthan</b>
8. Well No. <b>5</b>
9. Pool name or Wildcat <b>Blinberry Oil &amp; Gas (gas)</b>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>KB 3365' GL 3353'</b>

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator <b>Marathon Oil Company</b>	
3. Address of Operator <b>P.O. Box 2409, Hobbs, NM 88240</b>	
4. Well Location Unit Letter <b>C</b> : <b>660'</b> Feet From The <b>North</b> Line and <b>1980'</b> Feet From The <b>West</b> Line Section <b>11</b> Township <b>22-S</b> Range <b>37-E</b> NMPM <b>Lea</b> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>KB 3365' GL 3353'</b>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: **Place well on rod pump** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/18 MIRU pulling unit. ND wellhead. NU BOP. TOH w/tbg. RIH, tag fill at 5508. Clean out from 5508 to 5776'. Circ hole clean.

2/22 RIH, tag fill at 5726'. POOH. RIH w/bit. Clean out to 5726', POOH.

2/23 RIH w/bailer. Brakes let go, dropped swivel, stem parted, and dropped pipe. RIH w/spear, latch onto stem, POOH w/tbg. RIH w/bit and bailer. Clean out to 5717', POOH. RIH w/bailer, clean out to 5726', POOH.

2/28 RIH w/2 3/8" tbg. ND BOP. NU wellhead. RIH w/pump and rods. Load and test, OK.

3/1 POOH w/pump and rods. Made 2 swab runs. RIH w/pump & rods. Load & test, OK.

3/2 RD pulling unit.

SN at 5693'  
Btm of tbg 5713'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 3/3/00  
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

5  
C