## STATE OF NEW MEXICO INERGY AND MINERALS DEPARTMENT

.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	 
MOLTUBIATEID	
SANTA PE	
FILE	 
U.S.O.S.	 
LAND OFFICE	 
OPERATOR	

DISTRICT I SUPERIHISOR

## OIL CONSERVATION DIVISION

Form C-103

DISTRIBUTION	Р. О. ВО.		Revised 10-1-78	
SANTAFE	SANTA FE, NEW	MEXICO 87501		
FILE			State   Fee X	
U.S.O.S.				
LAND OFFICE			5. State Oil & Gas Lease No.	
OPERATOR			mmmmmm	
CLINDRY	NOTICES AND REPORTS ON	WELLS		
DUNUKT I	ALS TO DRILL OR TO DECPEN OR PLUG B	ACR TO A DIFFERENT RESERVOIR.	VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	
USE VAPPLIERTION	- Control of the cont		7. Unit Agreement Name	
OIL X WELL	OTHER-		Line Hope	
well (A) with an		8. Farm or Lease Name Lou Wortham		
Anadarko Production C	ompany			
Address of Operator			9. Well No.	
P. O. Box 806 Eunice, New Mexico 88231		10. Field and Pool, or Wildcat		
ocation of Well		10. Field and Pool, of Wilded		
North 660 rest from		on Leunile All		
UNIT LETTER	FEET FROM THE			
West	11 225	37E	~ (	
THE LINE, SECTION	TOWNSHIP		Ullimit HHHH	
mmmm	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County	
	3378 DF		Lea	
	Day To Indicate N	Nature of Notice, Report or C	other Data	
		SUBSEQUE	NT REPORT OF:	
NOTICE OF INTE	ENTION TO:		<u></u>	
	PLUS AND ABANDON	REMEDIAL WORK	ALTERING CASING	
AFORM REMEDIAL WORK	PEGG AND ADDRESS .	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
MPORARILY ABANDON		CASING TEST AND CEMENT JOS	_	
LL OR ALTER CABING	CHANGE PLANS	Re-enter ? &	A well X	
OTHER			the of starting any proposed	
Decette Proposed or Completed Opera	tions (Clearly state all pertinent det	ails, and give pertinent dutes, includi	ing estimated date of starting any proposed	
work) SEE RULE 1103.				
1. RUPU. Remove plugge	d hole marker.	oral manad Ekl	l asa stub @ 1207!	
2. TIH w/ 7 5/8" bit.	Tadded 37 Cod School Page 10 Jan 970 . Tadded 37 Cod School C 1407			
a more / 7 E /OU hit	The state of the contract of t			
PSI for 30 min. w/ n	o loss of press. Dril	lled cement plugs @ 2950	and books, lagged comment	
plug @ 4900'. TOH w	// bit.			
4. TIH w/ mill. Dress	TIH w/ mill. Dress off 5½" csg @ 1207'. TOH w/ mill.			
. Ran 30 jts. 1202' of 5½" 15.5# K55 R3 LT&C new csg.				
1' Dem Dyn 1 Chaded Neutron Lod and Cement Dond 109.				
RU CRC Wireline. Ran Dual spaced Neutron Doy Lite to Prilled.  RU B.J. Hughes. Cemented 5½" csg w/ 200 SX Class C cement w/ 2% CaCl. Circ cement to surface. Left plug @ 1100'. Plug down @ 10:32 A.M. 12-19-84.				
surface. Left plug	@ 1100'. Plug down @	10:32 A.M. 12-13-04.	лм 12-20-84. Drilled	
8. TIH $w/4 3/4$ " bit.	surface. Left plug @ 1100. Plug down @ 10:32 http://www.new.new.new.new.new.new.new.new.new.			
cement to 1207' KB.	Tagged plug @ 4900'.	Circ noie Clean. Ton	OF	
RU Welex Perforated L. San Andres zones 4636-42 and 4658-68 @ 1 SPF.				
10. TIH w/ 5½" PBP & PKF	O. TIH w/ 5½" PBP & PKR. Isolated L San Andres perfs. Acidized w/ 1500 gal 15% NEFE acid			
and 24 BS. ISDP 140	\ O #			
and the short 70 Dhla	)U#•			
11. Swapped back 70 Bbis	s load wtr and spent ac	cid.		
	load wtr and spent ac		240.000 SCF of N ISDP	
12. Shut down for Christ 13. RU Dresser Titan, tr	s load wtr and spent ac mas Holidays. ceated L. San Andres w/		240,000 SCF of N <sub>2</sub> . ISDP	
<ol> <li>Shut down for Christ</li> <li>RU Dresser Titan, tr</li> <li>2300#. (over to 2nd</li> </ol>	s load wtr and spent ac mas Holidays. ceated L. San Andres w/ page)	/ 3500 gal 20% HCL and 2	240,000 SCF of N <sub>2</sub> . ISDP	
<ol> <li>Shut down for Christ</li> <li>RU Dresser Titan, tr</li> <li>2300#. (over to 2nd</li> </ol>	s load wtr and spent ac mas Holidays. ceated L. San Andres w/ page)	/ 3500 gal 20% HCL and 2	240,000 SCF of N <sub>2</sub> . ISDP	
12. Shut down for Christ 13. RU Dresser Titan, tr 2300#. (over to 2nd  Thereby certify that the information about	s load wtr and spent actmas Holidays. reated L. San Andres w/ page) ove is true and complete to the best	/ 3500 gal 20% HCL and 2		
12. Shut down for Christ 13. RU Dresser Titan, tr 2300#. (over to 2nd  Thereby certify that the information about	s load wtr and spent actmas Holidays. reated L. San Andres w/ page) ove is true and complete to the best	/ 3500 gal 20% HCL and 2	240,000 SCF of N <sub>2</sub> . ISDP	
12. Shut down for Christ 13. RU Dresser Titan, tr 2300#. (over to 2nd  1 hereby certify that the information about	s load wtr and spent act mas Holidays. ceated L. San Andres w/ page)  ove is true end complete to the best	/ 3500 gal 20% HCL and 2		