

OIL CONSERVATION DIVISION

P. O. BOX 2038  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|   |   |
|---|---|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-  | 7. Unit Agreement Name                            |
| 2. Name of Operator<br>Gulf Oil Corporation   | 8. Farm or Lease Name<br>Hugh                     |
| 3. Address of Operator<br>P. O. Box 670, Hobbs, NM 88240  | 9. Well No.<br>7                                  |
| 4. Location of Well<br>UNIT LETTER C 660 FEET FROM THE North LINE AND 2310 FEET FROM THE West LINE, SECTION 14 TOWNSHIP 22S RANGE 37E NMPM. | 10. Field and Pool, or Wildcat<br>Blinebry & Tubb |
| 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County<br>Lea                                 |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|  |   |   |  |
|--|---|---|--|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>             |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/>        |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input checked="" type="checkbox"/> Repair DHC |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Blew casing and tubing down. Tag fill at 6578'. Attempted GIH with setting tool on wireline; hung up at 4713'. Cut wireline at 4650'. Swabbed. GIH with setting tool and close top sleeve at 5580'; test sleeve 1000#. Attempted open bottom sleeve at 5658'; could not open. Attempted open sleeve at 5590'; could not open. Perf 5600' with (2) 1/2" JH in tubing. Swabbed. Blinebry now producing up tubing, making 6 BO, 0 BW with 698 MCF. Tubb zone TA'd. Complete after DHC repair 10-25-81.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDPate TITLE Area Engineer DATE 10-28-81

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 00 28 1981

CONDITIONS OF APPROVAL, IF ANY:

001.001