Submit 3 Copies to Appropriate District Office

State of New Mexico

Energy inerals and Natural Resources Department

Form C-103

Revised 1-1-89

			N 171 V 1.714 // N	STATE TO A DE LEO	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA 2040 Pache			WELL API NO. 30-025-10272	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe,	MM	87505	5. Indicate Type of Lease STATE FEE	<u> </u>
DISTRICT III 000 Rio Brezos Rd., Aztec, NM 87410				6. State Oil & Gas Lease No.	لتنا
SUNDRY NOT	TICES AND REPORTS ON	WELL	 LS		///
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE	OPOSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FO -101) FOR SUCH PROPOSALS	EPEN ( CR PER	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Walden, EW	
Type of Well: OIL GAS WELL XX WELL	) OTHER			watten, Lw	
. Name of Operator Collins	& Ware, Inc.			8. Well No.	
Address of Operator 508 W. Wall, Suite 1		797	01	9. Pool same or Wildcat Blinebry Oil & Gas	-
. Well Location	980 Feet From The South			Feet From The West	Line
Section 15	Township 22S	Ran		NMPM Lea Cour	ıty
	10. Elevation (Show w	hether L 3400	OF, RKB, RT, GR, etc.)		
1. Check	Appropriate Box to India			eport, or Other Data	
NOTICE OF IN	TENTION TO:		SUB	SEQUENT REPORT OF:	
ERFORM REMEDIAL WORK	PLUG AND ABANDON			[X]======	_
	1 LOG AND ADMIDON	<u> </u>	REMEDIAL WORK	ALTERING CASING	L
[]	CHANGE PLANS		REMEDIAL WORK  COMMENCE DRILLING		_ ⊒ ד
EMPORARILY ABANDON				OPNS. PLUG AND ABANDONMEN	τ [
EMPORARILY ABANDON  ULL OR ALTER CASING  THER:  12. Describe Proposed or Completed Open	CHANGE PLANS	atails, and	COMMENCE DRILLING CASING TEST AND CE OTHER:	OPNS. PLUG AND ABANDONMEN	T
PULL OR ALTER CASING  DTHER:  12. Describe Proposed or Completed Open work) SEE RULE 1103.  This well has been a	change Plans  rations (Clearly state all pertinent der  a flowing well. On 1  16 RHBC pump. The	11/17	COMMENCE DRILLING CASING TEST AND CE OTHER:  d give pertinent dates, included 7/96 we went in	PLUG AND ABANDONMENT	
EMPORARILY ABANDON  ULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Openwork) SEE RULE 1103.  This well has been a 2" x 1 1/4" x 12" x flowing well to a put	CHANGE PLANS  Tations (Clearly state all pertinent des 1 flowing well. On 1 16 RHBC pump. The 1 mping well.	11/17 stat	CASING TEST AND CE OTHER:  d give periment dates, included 7/96 we went in the sus of this well	EMENT JOB PLUG AND ABANDONMENT  ding estimated date of starting any proposed  the hole with rods and a has been changed from a  Supervisor 11/21/96	T
EMPORARILY ABANDON  FULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Open work) SEE RULE 1103.  This well has been a 2" x 1 1/4" x 12' x flowing well to a put flowing well to a put significant section.	Tations (Clearly state all pertinent des flowing well. On 16' RHBC pump. The amping well.	11/17 stat	CASING TEST AND CE OTHER:  d give periment dates, included 1/96 we went in the sus of this well.	Supervisor  Supervisor  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PATE  PLUG AND ABANDONMENT  PATE  PLUG AND ABANDONMENT  PATE  PATE  11/21/96  (915)	
EMPORARILY ABANDON  FULL OR ALTER CASING  OTHER:  12. Describe Proposed or Completed Open work) SEE RULE 1103.  This well has been a 2" x 1 1/4" x 12" x flowing well to a put flowing well to a put significant flowing with the information above is to stonature  Type or Frint Name  Dianne	CHANGE PLANS  Tations (Clearly state all pertinent des 1 flowing well. On 1 16 RHBC pump. The 1 mping well.	11/17 stat	CASING TEST AND CE OTHER:  d give periment dates, included 1/96 we went in the sus of this well.	Supervisor DATE PLUG AND ABANDONMENT DATE	
Thereby certify that the information above is to signature	Tations (Clearly state all pertinent des flowing well. On 16' RHBC pump. The amping well.	11/17 stat	CASING TEST AND CE OTHER:  d give periment dates, included 1/96 we went in the sus of this well.	Supervisor  Supervisor  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  PATE  PLUG AND ABANDONMENT  PATE  PLUG AND ABANDONMENT  PATE  PATE  11/21/96  (915)	