

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-10274 ✓
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name E.W. WALDEN
8. Well No. 6
9. Pool name or Wildcat DRINKARD & TUBB

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator AMERADA HESS CORPORATION	3. Address of Operator DRAWER D, MONUMENT, NM 88265	4. Well Location Unit Letter M : 731 Feet From The SOUTH Line and 731 Feet From The WEST Line Section 15 Township 22S Range 37E NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3406' DF
--	---	--	---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER: SURFACE COMMINGLE GAS PRODUCTION <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

PLAN TO MIRU PU. RIG UP WIRELINE EQUIPMENT & RUN TUBING STOP IN 2" BUTTRESS TBG. REMOVE WELLHEAD & INSTALL TREE ASSEMBLY. RELEASE PKR. & TOH W/TBG. & PKR. TIH W/REPAIRED OR REPLACEMENT PRODUCTION PKR., SN W/RUPTURE DISK IN PLACE ON 2" TBG. TO ± 6228'. HYDROSTATIC TEST TUBING GOING IN THE HOLE TO 5000# & SET PKR. REMOVE TREE ASSEMBLY. INSTALL WELLHEAD. TIH W/WT. BAR & RUPTURE DISC. & RETURN WELL TO PRODUCTION. SURFACE COMMINGLE GAS PRODUCTION FR. DRINKARD & TUBB ZONES.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE SUPV. ADM. SVC. DATE 5-20-93  
TYPE OR PRINT NAME R.L. WHEELER, JR. TELEPHONE NO. (505) 393-2144

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

MAY 27 1993

RECEIVED

MAY 26 1999

OLD HOBBS OFFICE