

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG. USE FOR A DIFFERENT PAPER OR, USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator ANADARKO PRODUCTION COMPANY		
Address of Operator P. O. Box 806, Eunice, New Mexico 88231		
Location of Well UNIT LETTER E , 1980 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 15 TOWNSHIP 22-S RANGE 37-E N.M.P.M.		

7. Unit Agreement Name
8. Farm or Lease Name E. W. Walden
9. Well No. 1
10. Field and Pool, or Well Section Penrose-Skelly
11. Elevation (Show whether DE, RE, GR, etc.) 3407' GR
12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	FINISHING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and all pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU;
2. Ran tubing to 3652';
3. Pumped 300 sks Class "C" cmt. w/4% gel, 5# Gilsonite & 1/4# Flocele per sack, 4-21-76;
4. Tagged top cement @ 2790', 4-22-76;
5. Loaded hole with 10.2# salt gel mud;
6. Spotted 20 sk plugs @ 2500', 1200', 300', and surface;
7. Installed dry hole marker & removed anchors;
8. Levelled location;
9. Location now ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Herb Henderson TITLE Area Supervisor DATE 04-24-76

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: