



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-K358.4
Approval expires 12-31-60.

Land Office Las Cruces
Lease No. 20 02570b
Unit 249

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL <u>Landfrac</u>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Elliott 5-17

March 25, 1957

Well No. 2 is located 660 ft. from N line and 600 ft. from E line of sec. 17
1/4 Sec. 17 (1/4 Sec. and Sec. No.)
Penrose Kelly (Field)
27-3 (Twp.) 37E (Range) 6N-4E (Meridian)
Lea (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well is presently shut in. It is intended to return this well to production by the following means: Load hole with oil, pull tubing. Run 4" log. Set 2" tubing at approximately 3570' (casing set at 3530'). Landfrac open formation, open hole 3629-3724', thru tubing and tubing-casing annulus with 10,000 gallons lease crude, with 1% sand and 0.1% fluoride per gal. Recover load; test.

A subsequent report will be submitted upon completion of work.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 60
San Jose, New Mexico

By W. L. G. G. G.

Title District Superintendent