

**UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT**

I am approved.  
Bureau No. 1004-0135  
Expires August 31, 1985  
LEASE REGISTRATION AND SERIAL NO.  
NM - 1410

N.M. OIL & GAS COM.  
P.O. BOX 1980  
HOBBS NEW MEXICO 87401

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT--" for such proposals.)

<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. NAME OF OPERATOR <b>Zia Energy Inc</b></p> <p>3. ADDRESS OF OPERATOR <b>P.O. Box 2219, Hobbs, NM 88241</b></p> <p>4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <b>1650' FNL &amp; 1650' FEL</b></p> <p>14. PERMIT NO. <b>30-025-10339</b></p>	<p>6. IF INDIAN, ALLOTTEE OR TRIBE NAME</p> <p>7. UNIT AGREEMENT NAME</p> <p>8. FARM OR LEASE NAME <b>Federal</b></p> <p>9. WELL NO. <b>2</b></p> <p>10. FIELD AND POOL, OR WILDCAT <b>Eunice San Andres-SW</b></p> <p>11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>17-22S-37E</b></p> <p>12. COUNTY OR PARISH <b>Lea</b></p> <p>13. STATE <b>NM</b></p>
<p>15. ELEVATIONS (Show whether DF, RT, OR, etc.) <b>3413' RKB</b></p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Other) **Perforate Add'l SA zone**

\*(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. RU well servicing unit. Pull rods, pump and tubing.
2. Install BOP.
3. Perforate additional San Andres zone with five jet shots from 3894' - 3898'
4. Acidize perfs. with 600 GA - through tubing, below packer set at 3860'.
5. Pull and lay down packer. Run tubing with a 2 3/8" x 1 3/4" x 16' tubing pump barrel - run 1 3/4" plunger and rods..
6. Place well on production.

18. I hereby certify that the foregoing is true and correct

SIGNED *Jarvis Nelson* TITLE Engineer DATE 6/27/96

(This space for Federal or State office use)

APPROVED BY *[Signature]* TITLE *[Signature]* DATE 7/22/96

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side