

NO. COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT L-1" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/> YY</p> <p>5. State Oil & Gas Lease No.</p>
<p>1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p>		<p>7. Unit Agreement Name</p>
<p>2. Name of Operator Amerada Hess Corporation</p>		<p>8. Farm or Lease Name E. Wood</p>
<p>3. Address of Operator Drawer "D", Monument, New Mexico 88265</p>		<p>9. Well No. 6</p>
<p>4. Location of Well UNIT LETTER <u>A</u> <u>713</u> FEET FROM THE <u>North</u> LINE AND <u>713</u> FEET FROM <u>East</u> LINE, SECTION <u>22</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> N.M.P.M.</p>		<p>10. Field and Pool, or Equivalent Ellenburger</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.)</p>		<p>11. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to: Kill well with treated water, pull rods, pump and tubing. Set retrievable bridge plug above productive ELLENBURGER Zone. Perforate at 2965' (150' above cement top outside 5 1/2" casing). Squeeze with cement, run temperature survey, drill out cement and test squeeze job. Recover bridge plug, re-run production equipment and return to production.

This workover is to comply with Commission No. R-5003.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED MP Blush TITLE Supver., Admin. Services DATE 9-22-75

Orig. Signed by
John Rungen
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: