CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy nerals and Natural Resources Department

Form C-103

Revised 1-1-89

DISTRICT P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, N	M 87505	30-025-10392 5. Indicate Type of Lease
DISTRICT III			STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
	ICES AND REPORTS ON WEI		
DIFFERENT RESE	OPOSALS TO DRILL OR TO DEEPEN RVOIR. USE "APPLICATION FOR PE	I OR PLUG BACK TO A RMIT"	7. Lease Name or Unit Agreement Name
1. Type of Well:	-101) FOR SUCH PROPOSALS.)		Wood, Eugene
MET X MET OF CAS	OTHER		
2. Name of Operator			8. Well No.
Collins & Ware, Inc. 3. Address of Operator			9. Pool name or Wildcat
508 W. Wall, Suite 1200, Midland, Texas 79701			Blinebry Oil & Gas
4. Well Location	_		
Unit Letter A: 73	Feet From The North	Line and 641	Feet From The East Line
Section 22	Township 22S Ra	inge 37E	NMPM Lea County
	10. Elevation (Show whether	DF, RKB, RT, GR, etc.)	
	3351		
	Appropriate Box to Indicate 1		_
NOTICE OF INT	ENTION TO:	SOB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CE			EMENT JOB
OTHER:		OTHER: Plugbac	k to Blinebry
12. Describe Proposed or Completed Opera work) SEE RULE 1103.	tions (Clearly state all pertinent details, an	d give pertinent dates, inclu	ding estimated date of starting any proposed
10/02/96 Set Alpha 5 1	1/2" x 10K CIBP at 6175	with 35' of ce	ement on top.
10/03/96 Set Howco ret	tainer at 5875 . Sting	into retainer a	nd squeeze perfs with 200 sx
	PBTD at 5865 .	1! - 5837! (ON 6	noles). Set packer at 5341'
and acidize p	perfs with 4000 gals 15%	% Ferchek SC aci	d with ball sealers.
10/07/96 Frac perfs (5421' - 5837') with 103,000 gals Delta Frac 25 with 30# per 1000			
gallons FL4 i	in pad using 275,000# 16	6/30 Ottawa sand	l.
10/09/96 Bailing sand. Have sand falling in, very sticky. 10/10/96 Bail down to 5840'. Hook up production equipment and start testing.			
	ספטים אססא up product ing equipment.	cion equipment a	ing start testing.
,,			
			sidered zone abandoned and will
no Longer be	carried on the C-115 re	eport.	
I hereby certify that the information above is true	and somplete to the best of my knowledge and	belief.	
SKINATURE / Claim	Dumill III	Production S	upervisor DATE 10/21/96
TYPEOR PRINT NAME Dianne Sum	ırall		TELEPHONE NO. (915) 687-34
(This space for State Use)	en e		
(This space for State Use)			େ ଅଧିକ ଅଟ ୍ର
APPROVED BY	m	LE	DATE