NEW	MEXICOLO	<b>L</b> CONSERVATION	COMMISSION	•
	S	unta Fe, New Mexico	COMMISSION FICE	ucç

MISCELLANEOUS NOTICES ES PM 3:22

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

i.	Indicate Nature of Notice by Che	cking Be	low	
NOTICE OF INTENTION TO CHANGE PLANS	Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Notice of Intention to Plug Back		Notice of Intention to Set Liner	
TOTICE OF INTENTION O SQUEEZE	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Votice of Intention o Gun Perforate	Notice of Intention (Other)		Notice of Intention (Other)	- Sandoil Joh
OIL CONSERVATION COMMISSIC SANTA FE, NEW MEXICO	ON Eunice, New Nexico		March 26, 1	956
Gentlemen:	(-13-17)			•
	to do certain work as described below at			
Amerada Petroleum Corp	peration - E. Wood	•	Well No7	in A (Unit)
NE / 1/4 NE / 1/4 of Sec 2	perator) 2, T, R, R, R	,NMPM	, Tubb	Pe
(40-acre Subdivision)				
	FILL DETAILS OF PROPOSED	PLAN (	OF WORK	
Rig up, pull separation	FULL DETAILS OF PROPOSED I LLOW INSTRUCTIONS IN THE RULI I sleeve and run blank-off to Lions at 5945' to 6110' (epp	es and col.	REGULATIONS)  Sandoil down tubing Tabb) with 25,000 g	allons
Rig up, pull separation	slow instructions in the ruli is slowe and run blank-off to ions at 5945' to 6110' (opposed) sand. Sumb and flow to to	es and col.	REGULATIONS)  Sandoil down tubing Tabb) with 25,000 g	allons
Rig up, pull separation casing through perferat refined oil and 20,000#	slowe and run blank-off tions at 5945' to 6110' (opposed and flow to to all production status.	eol. osite st. R	REGULATIONS)  Sandoil down tubing Tabb) with 25,000 g	allons
Rig up, pull separation casing through perferat refined oil and 20,000# and put well back on da	slowe and run blank-off tions at 5945' to 6110' (opposed and flow to to all production status.	es and col. osite st. R	Sandoil down tubing Tabb) with 25,000 generation slaver Company or Operator Handau	allons .eeve
Rig up, pull separation casing through perferat refined oil and 20,000# and put well back on da	slowe and run blank-off tions at 5945' to 6110' (epp sand. Such and flow to tellal production status.  By	es and col. osite st. R	Sandoil down tubing Tubb) with 25,000 g e-run Separation sl	well to: