Office		w Mexico		Form C-1
District I	Energy, Minerals and	Natural Resources	<u> </u>	Revised March 25, 1
1625 N. French Dr., Hobbs, NM 87240			WELL API	
District II 811 South First, Artesia, NM 87210	OIL CONSERVA			-025-10416
District III	2040 South Pacheco		ľ	ype of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, 1	NM 87505	STAT	
2040 South Pacheco, Santa Fe, NM 87505			6. State Oil a	& Gas Lease No. 5-A
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPORTION OF THE PROPOSALS.) 1. Type of Well:	CES AND REPORTS ON OSALS TO DRILL OR TO DEE CATION FOR PERMIT" (FOR!	EPEN OR PLUG BACK TO A	`	ne or Unit Agreement Name:
Oil Well X Gas Well	Other		TRACT 14	
2. Name of Operator			8. Well No.	
Anadarko Petroleum Corp.			24-02	
3. Address of Operator			9. Pool name	
P.O. Box 2497 Midland, TX 7	9702		LANGLIE-MAT	TIX SR QN GRBG
4. Well Location				
Unit Letter:	1980 feet from the	SOUTH line and	1980 fe	et from the <u>EAST</u> li
Section 22	Township 22	S Range 37E	NMPM	County LEA
	10. Elevation (Show wh	ether DR, RKB, RT, GR,	etc.)	· warranger
		3337' GL		e considération e que que en la considération e que que la considération e la considération e la considération e
11. Check A	Appropriate Box to Ind	licate _l Nature of Notic	e, Report, or C	Other Data
NOTICE OF INT	ENTION TO:	SU	IBSEQUENT	REPORT OF:
PERFORM REMEDIAL WORK [X]	PLUG AND ABANDON	REMEDIAL WOR	<	☐ ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	☐ PLUG AND
PULL OR ALTER CASING	MULTIPLE	CASING TEST AN	חו	ABANDONMENT
OLL OR ALTER CASING	COMPLETION	CEMENT JOB	lD	
OTHER:		OTHER:		
JINER.				
12. Describe Proposed or Complete of starting any proposed work). or recompilation.		-		
12. Describe Proposed or Complete of starting any proposed work).	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta		ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI.	eltiple Completions: Atta	ch wellbore diagr	ram of proposed completion
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	LEAK @ 1600 - 1630'. SHOE. PERFORM MECHN	ich wellbore diagr	ram of proposed completion
 Describe Proposed or Complete of starting any proposed work). or recompilation. MIRU. SET RBP @ 1680 SPOT 5 BBL MARA-SEAL SQZ 2 - 3 BBLS INTO L CLEAN OUT POLYMER, TE 	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	LEAK @ 1600 - 1630'. SHOE. PERFORM MECHN	ich wellbore diagr	ram of proposed completion
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	EAK @ 1600 - 1630 . SHOE. PERFORM MECHN est of my knowledge and be	ICAL INTEGRITY	TEST
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	LEAK @ 1600 - 1630'. SHOE. PERFORM MECHN	ICAL INTEGRITY	TEST: R DATE 01/03/02
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	EAK @ 1600 - 1630 . SHOE. PERFORM MECHN est of my knowledge and be	ICAL INTEGRITY	TEST: R DATE 01/03/02
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	EAK @ 1600 - 1630 . SHOE. PERFORM MECHN est of my knowledge and be	ICAL INTEGRITY	TEST R DATE01/03/02
12. Describe Proposed or Complete of starting any proposed work). or recompilation. 1. MIRU. SET RBP @ 1680 2. SPOT 5 BBL MARA-SEAL 3. SQZ 2 - 3 BBLS INTO L 4. CLEAN OUT POLYMER, TE 5. TIH W/INJECTION PKR A	SEE RULE 1103. For Mu . POLYMER ACROSS MINOR L EAK. SD FOR 2 DAYS. ST CSG TO 500 PSI. ND SET WITHIN 100' OF	EAK @ 1600 - 1630 . SHOE. PERFORM MECHN est of my knowledge and be	ICAL INTEGRITY	TEST DATE01/03/02