

COPIES RECEIVED	
DISTRIBUTION	
DATE	
BY	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
NMJ-528

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas Pacific Oil Company, Inc.	8. Farm or Lease Name Boyd
3. Address of Operator P. O. Box 4067, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER G 2310 FEET FROM THE North LINE AND 2310 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 22-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3320 GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU Wireline Unit. Run & set CIBP @ 6200' via wireline. Dump 35' cmt. on CIBP.
- Set another CIBP @ 4600' & cmt. retainer @ 2450'. RD wireline unit.
- MIRUPU. Run 2-7/8" tbg. & tie into retainer.
- Squeeze csg. leaks w/1100 sxs. cmt. Displace cement within 1 bbl. of retainer.
- Circ. hole w/mud laden fluid.
- Pull tbg., remove wellhead, place 10 sx cmt. plug @ surface & install marker.
- RDMOPU

100' plug required in 5 1/2" lgs opposite T11 of 5elt

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *L. Wright* TITLE Area Superintendent DATE September 22, 1975

APPROVED BY *[Signature]* TITLE *[Signature]* DATE *[Signature]*

CONDITIONS OF APPROVAL, IF ANY: