

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.O.B.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

C CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-79

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

|                                                                                                                                                                                                         |                                            |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                                                                        | 7. Unit Agreement Name                     |
| 2. Name of Operator<br>Sun Exploration & Production Co.                                                                                                                                                 | 8. Farm or Lease Name<br>Boyd              |
| 3. Address of Operator<br>P. O. Box 1861 - Midland, Texas 79702                                                                                                                                         | 9. Well No.<br>3                           |
| 4. Location of well<br>UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM<br>THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>22-S</u> RANGE <u>37-E</u> NMPM. | 10. Field and Pool, or Wildcat<br>Drinkard |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3318' GR                                                                                                                                               | 12. County<br>Lea                          |

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                           |                                                      |                                                                   |
|------------------------------------------------|-------------------------------------------|------------------------------------------------------|-------------------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>               | ALTERING CASING <input type="checkbox"/>                          |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/>                     |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOBS <input type="checkbox"/> | OTHER <input checked="" type="checkbox"/> Test for leak, Run Logs |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1105.

- 3-10 MIRU DA & S WS/POH LD 2-3/8 tbg (201 jts)/RIH w/4-3/4 RB on 2-7/8 tbg to 384'.
- 3-11 Cont 1 Hr. w/4-3/4 RB & 2-7/8 tbg tag CIBP @ 6370/POH/RIH w/5½ RBP & RDG (Baker) pkr, Set RBP 6240 Test RBP 1500# OK PKR @ 6229 test cst 800# Leak 700# in 5min.
- 3-12 Raise & set RDB in various places Test w/comm to csg/POH to exam. and change out PKR/RIH w/5½ FDPKR on 2-7/8 tbg/set PKR in var. intervals Found csg leaks between 3774-4093/4093-6240 test 1000# OK/3774-surf test 1000# OK/lower PKR tag & latch RBP @ 6240/ PU to 6140.
- 3-13 Raise & Reset RBP @ 4093/Set PKR 3774/In 4 hrs swab, 6B0 9 BW .
- 3-15 Tag fl w/swab 2900/Lower PKR latch RBP @ 4093/POH LD 2-7/8 tbg PKR & RBP.
- 3-16 Schlum Run CNL 6332-1300.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dec Ann Kemp TITLE Asst. Asst. II DATE 4-6-83

APPROVED BY Ronald M. [Signature] TITLE OIL & GAS INSPECTOR DATE APR 11 1983

CONDITIONS OF APPROVAL, IF ANY: