

Cont. - Boyd #5

Page 3

- 3-29 Finish 1 H w/4-3/4 csg swage/tag & work thru tite spot 2930-44 fell free/ lower & tag fish 3149/POH?RIH w/4-11/16 X 3-1/16 overshot and 2-7/8 tbg / tag fish @ 3149 - Unable to latch / POH / RIH w/4-11/16 X 3-1/8 overshot on 2-7/8 tbg/tag & latch fish @ 3149/ unable to Rlse seal Assy in Model D pkr in 1 hr.
- 3-30 Rlse seal assy from Model D pkr/POH w/fishing string & fish Rec 97 jts jts 2-3/8 tbg sliding sleeve, 2-2-3/8 tbg subs & seal assy - Left SN & 2 jts 2-3/8 NU tbg. in hole.
- 3-31 RIH w/4-3/4 csg swage bumper sub jars 6-3- $\frac{1}{2}$ DCs on 2-7/8 tbg-Tag & work thru tite spots 2883-2944/POH/RIH w/5 $\frac{1}{2}$ RBP (Model C) & FB pkr on 2-7/8 tbg - Tag @ 2867- Fell thru -Tag @ 2883 unable to lower past/POH w/RBP & pkr (cups on RBP cut) RIH w/4-3/4 csg swage Bumper Sub jars 6-3 $\frac{1}{2}$ DC's on 2-7/8 tbg Tag & work thru tite spot 2883 - Lower to 3100/POH/RIHw/ 5 $\frac{1}{2}$ (Model G) RBP on 2-7/8 tbg to 2883 tag & unable to lower Past/POH.
- 4-1 RIH w/3-1/8 DC 4-3/4 DC 4-3/4 string Mill, 6-3 $\frac{1}{2}$ DC on 2-7/8 tbg tag @ 2883 - Fell thru to 2889. Mill on cst 2889-91 in 7 hrs. Rec metal & cmt/ PU to 2829.
- 4-5 POH w/4-3/4 string mill DCs & tbg/change out string mills/RIH w/milling Ass'y on 2-7/8 tbg/tag @2891 - Fell thru - lower tag & mill 2901 - 2902 in 7 hrs/circ clean/PU to 2774.
- 4-6 Lower Mill tag & mill 2902 - 18 16' in 9 $\frac{1}{2}$ hrs / circ clean/PU to 2774.
- 4-7 POH w/string mill & Ass'y found 3-1/8 DC below mill badly worn w/no wear on mill indicating 3-1/i DC outside csg/LD DCs & 2-7/8 tbg from Derrick/ LD rods from Derrick / rig rel.