

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p>
<p>1. Name of Operator Phillips Petroleum Company</p>		<p>5. State Oil &amp; Gas Lease No. —</p>
<p>2. Address of Operator Room 711, Phillips Building, Odessa, Texas 79761</p>		<p>7. Unit Agreement Name —</p>
<p>3. Location of Well UNIT LETTER <u>L</u> <u>661</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>24</u> TOWNSHIP <u>22S</u> RANGE <u>37-E</u> NMPM.</p>		<p>8. Farm or Lease Name Sims</p>
<p>15. Elevation (Show whether DF, RT, GR, etc.) 3322' GR, 3335' RKB</p>		<p>9. Well No. 1</p>
<p>12. County Lea</p>		<p>10. Field and Pool, or Wildcat Blinebry - Gas</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

<p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <u>D &amp; A Zone Only</u> <input checked="" type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOBS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input type="checkbox"/></p>
--	---	---	--

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to move in rig, kill well, install BOP and pull tbq and packer.

Spot 50 sx Class H cement w/1/4# Flocele/sx from 5070 to 5500' across Blinebry perfr 5430-84', reverse out excess cement, plug and abandon Blinebry. Clean out plugs 5485' to 7005, open hole to 7320'. Test, treat, and complete Drinkard zone open hole interval from 7005 - 7320'.

BOP equipment: Series 900, 3000# WP, double, with one set pipe rams, one set blind rams. Manually operated.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

W. J. Mueller TITLE Senior Reservoir Engineer DATE 4-23-75

PREPARED BY John W. Bryan TITLE Geologist DATE 4-23-75

CONDITIONS OF APPROVAL, IF ANY: