

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002510466
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Baker 'A'
8. Well No. 4
9. Pool name or Wildcat Langlie Mattix 7RQG

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Texaco Producing Inc	
3. Address of Operator P.O. Box 730 Hobbs, New Mexico 88240	
4. Well Location Unit Letter C : 660 Feet From The North Line and 1980 Feet From The West Line Section 26 Township 22S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3330 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

BAKER "A" WELL NO. 4 (WI 100%)  
660' FNL, & 1980' FWL, SECTION 26, T-22-S, R-37-E  
TD: 6430'  
CSG: 5 1/2" SET @ 6410', PBTD: 3700'  
P&A COMPLETED: 1-20-89

MIRU BABER 1-11-89. PULL RDS & PMP. B/O RDS. LATCH ONTO TBG & WAS STUCK. RAN JARS ON RDS. FP TBG -100% STUCK @ 3009'. CUT OFF @ 2994'. PULL 20' & STUCK. COLLAR STUCK @ 2961'. CUT OFF @ 2915'. RAN OS & JARS & LATCH FSH @ 2915'. RAN SWEDGE & TAG @ 2948'. SWEDGE FR 2948-2963'. RAN O.S. & JARS. CAUGHT FSH @ 2884'. RAN SHOE & WP & TAG @ 2953'. MILL FR 2953-2976'. CMT RET @ 2900'. PMP 70 SX CL 'C' DN RET. SPOT 25 SX PLUG FR 2900-2685'. SPOT 25 SX PLUG FR 1170-955'. SPOT 10 SX PLUG @ SURF. CUT OFF WH. INSTL DRYHLE MARKER. CHANGE STATUS TO P&A EFFECTIVE 1-20-89.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.W. Johnson TITLE Engr. Asst. DATE 1/31/91  
TYPE OR PRINT NAME L.W. Johnson TELEPHONE NO. (505) 397-0426

(This space for State Use)

APPROVED BY R.A. Padilla TITLE OIL CONSERVATION INSPECTOR DATE FEB 01 1991  
CONDITIONS OF APPROVAL, IF ANY: