TRIBUTION			Form C-103 Supersedes Old
at - FE	NEW MEXICO OIL CONS	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			Effective 1-1-65
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			
OPERATOR			5. State Oil & Gas Lease No.
			5, State Off & Gas Lease No.
SUND	NOTICES AND DEPOSTS ON		
(DO NOT USE THIS FORM FOR P USE "APPLIC	DRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG E ATION FOR PERMIT	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)	
			7. Unit Agreement Name
WELL WELL	OTHER-		
2. Name of Operator			8. Farm or Lease Name
Skelly 011 Company	r		Baker "A"
3. Address of Operator			9. Well No.
P () Boy 1351 Md	dland, Texas 79701		
4. Location of Well	uland, lexas / ///l		4 10. Field and Pool, or Wildcat
UNIT LETTER,,	660 FEET FROM THE North	LINE AND FEET FRO	M Langlie-Mattix
	• •		
THE West LINE, SEC	TION 26 TOWNSHIP228	RANGE NMP	• <u>() </u>
, , , , , , , , , , , , , , , , , , ,			
$\boldsymbol{\lambda} = (\boldsymbol{\lambda} = \boldsymbol{\lambda} =$	15. Elevation (Show whether	-	12. County
$\frac{16}{16}$		330' DF	Lea
Check	Appropriate Box To Indicate N	lature of Notice, Report or O	ther Data
NOTICE OF	INTENTION TO:		IT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
		OTHER Plug back and re	complete in Queen XX
OTHER		(Penrose Sand)	
		·	
17. Describe Proposed or Completed (Operations (Clearly state all portinent day		

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Moved in pulling unit 9-20-73.
- 2) Set 5-1/2" bridge plug at 3700' and capped with cement to 3679'.
- 3) Tested casing and bridge plug to 1500# for 15 minutes: held okay.
- 4) Perforated 5-1/2" casing with two .38" shots at each of the following places: 3596', 3600', 3614', 3630', and 3647'.
- 5) Treated perforations 3596-3647' with 1250 gallons of 15% XW acid, using 15 ball sealers.
- 6) Swabbed back load water, no oil.
- 7) Frac treated perforations 3596-3647' with 10,000 gallons of 9# gelled brine water and 15,000# of 20/40 sand.
- 8) Swabbed and flowed perforations 3596-3647' 10-1/2 hours, 5 barrels of oil and 78 barrels of load water.
- 9) Perforated 5-1/2" casing with two .38" shots at each of the following places: 3488', 3496', 3501', 3509', 3522', 3530', 3540', 3550', 3557', and 3566'.
- 10) Set bridge plug at 3580' and packer at 3239'.
- 11) Treated perforations 3488-3566' with 250 gallons of 15% MBA acid and 1000 gallons of 15% NE acid, using 28 ball sealers.
- 12) Swabbed perforations 3488-3566' 7 hours, 1 barrel of oil, 71 barrels of load water and 65 barrels of formation water.

18. I hereby certify that the information above is true and complete to the best (FOR LINE CONTINUED OF bpage 2)

(Signed) D.	D. C. Crow	TITLE Lead Clerk	DATE 10-12-73
APPROVED BY		TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY: