

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Water injection well</b>		7. Unit Agreement Name <b>Langlie Mattix Penrose Sand Unit</b>
2. Name of Operator <b>Anadarko Production Company</b>		8. Farm or Lease Name <b>Tract No. 13B</b>
3. Address of Operator <b>P. O. Box 247, Hobbs, N.M. 88240</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>D</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>27</b> TOWNSHIP <b>22S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Langlie Mattix</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3341' DF</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rigged up well servicing unit on 10-19-70 & pulled 2-3/8" plastic lined tubing with packer.
2. Rigged up reverse circulation equipment with 2-7/8" tubing and 15 jts. of 2-7/8" drill Pipe.
3. Cleaned out the shot hole interval from top of cavings to total depth of 3679'.
4. Remove clean out string and rerun 2-3/8" plastic tubing with packer.
5. Place well back on injection. 10-24-70

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>M. J. Nelson</i></u>	TITLE <u>District Superintendent</u>	DATE <u>11-2-70</u>
APPROVED BY <u><i>[Signature]</i></u>	TITLE <u>SUPERVISOR DISTRICT</u>	DATE <u>NOV - 3 1970</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

NOV - 9 1970

OIL CONSERVATION COMM.  
HO2ES, N. M.