## N''' MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## **MISCELLANEOUS NOTICES**

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or its agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature	of notice by	checking be	elow:			
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	1	OTICE OF I	NTENTION LY TREA	N TO SHO T WELL	OOT OR	
NOTICE OF INTENTION TO CHANGE PLANS	XXXX	OTICE OF IN			OR	-
NOTICE OF INTENTION TO REPAIR WELL	1	OTICE OF IN	TENTION	TO PLUG	WELL	
NOTICE OF INTENTION TO DEEPEN WELL						
H bbs. New 1	lexico.		No	wambar	28 1936	
		Place		TE III DEST	28 1956 Date	
OIL CONSERVATION COMMISSION,						
Santa Fe, New Mexico. Gentlemen:						
Following is a notice of intentiton to do certain worl	as describe	l below at th	e			
Skeily Qi. Company J.V.	laker	w	ell No.	3_	in CNE/4	.NW/4
Company or Operator Lease					•	
of Sec. 27 , T. 22 , R. 37	, N. M.	P. M.,	South	Enurce		Field,
L 28 County.						
and then drill well in with cable 9-5/8 - 36" Seamless casing 7" OD - 24 Seamless casing	to be set	at appro	ximate	ly 200'	with 125 /for surf	sacks ace stri
Approved Movember 30, 1936.						
,		Skelly	<u>r 011 c</u>	<b>O</b> mbany		
xcept as follows:	<u> </u>	Skel lj	7 0 11 Co	Ompany upany or O	perator	<del></del>
he 7" string of casing must be cement	ed By	Skelly	7 011 0 Con	Ompany upany or O	perator	<u>-</u>
he 7" string of casing must be cement ith a two-stage job. The lower stage	shall 2,	Skel ly	imi	inez	<u>-</u>	
he 7" string of casing must be cement ith a two-stage job. The lower stage ill to the base of the salt and the w	shall Pos		Z <i>im()</i> Distri	ct supe	perator rintendad arding well	. •
he 7" string of casing must be cement ith a two-stage job. The lower stage ill to the base of the salt and the utage shall fill back to the surface p	shall pos pper Pos ipe.	Send o	Distri ommunic	ct supe	rintendad	. •
he 7" string of casing must be cement ith a two-stage job. The lower stage ill to the base of the salt and the w	shall pper Posipe.	<b>Send</b> c	Distri Ommunica Ckel ly	ct superations reg	rintendad arding well wany	to
he 7" string of casing must be cement ith a two-stage job. The lower stage ill to the base of the salt and the utage shall fill back to the surface p	shall pper Posipe.	<b>Send</b> c	Distri Ommunica Ckel ly	ct superations reg	rintendad	to