NEV 1EXICO OIL CONSERVATION CO 1ISSION

Santa Fe, New Mexico

	\square
MAY 1 4 1937 P	
MEDENTE	

MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut-off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below:

	N BEGINNING DRILLING OPERATION	8	REPORT ON REPA		
	N RESULT OF SHOOTING OR CHEMICA MENT OF WELL	L I	REPORT ON PULL ALTERING CAS	ING OR OTHERWISE	
REPORT O SHUT-O	N RESULT OF TEST OF CASING FF		REPORT ON DEEP	ENING WELL	
REPORT OF	N RESULT OF PLUGGING OF WELL				
<u> </u>		Hobbs,	New Mexico	May 12,	1957.
	ERVATION COMMISSION, New Mexico.		Place	Date	
Gentlemen	:				
Following	is a report on the work done and the Skelly 011 Company		The loop	▲	in the
	CS: C/mpant of AOperator	27	Lease 22	\$7	. N. M. P. M.,
	Penrose Area Field.	······································	Lea		, IX. M. F. M.,
The dates (of this work were as follows:		April 10th		00untj.
	intention to do the work was	submitted	n Form C-102 on	April 9th	1,57
and approv	val of the proposed plan was [was h	🚺 obtained. (0	Cross out incorrect w	vords.)	
	DETAILED ACCOUNT OF	F WORK DO	NE AND RESU	LTS OBTAINED	
	TD-5610'. Well shot with anchor 5600' to 5610'. Sh Shot exploded on time and spent cleaning out. Was n re-caving. Two inch tubin	tot tamped w hole bridge boossary to	ith approx. the d itself. Apr pull tubing to	ree yards gravel il loth to May f wice due to hole	L. Muha D
	anchor 5600" to 5610". Sh Shot exploded on time and	hole bridge bole bridge bolessary to lg set at 35 hours thru stimated 600	th approx. the d itself. Apr pull tubing to 75°, Packer so 18/64 choke with H.	ree yards gravel il loth to May a wice due to hole t at 3292°. 5-1 th CP \$ and TP	L. 9 1h 12 -57 , 100.
	enchor 3600° to 3610°. Sh Shot exploded on time and spent cleaning out. Was n re-caving. Two inch tubin Well flowed 76 bbls in 12 While cleaning out, gas es V. B. Peck	hole bridge bole bridge bolessary to lg set at 35 hours thru stimated 600	th approx. the d itself. Apr pull tubing to 75°, Packer so 18/64 choke with H.	ree yards gravel il loth to May f wice due to hole t at 3292°. 5-3	L. 9 1h 12 -57 , 100.
	enchor 3600° to 3610°. Sh Shot exploded on time and spent cleaning out. Was n re-caving. Two inch tubin Well flowed 76 bbls in 12 While cleaning out, gas es V. B. Peck	hole bridge bole bridge bolessary to lg set at 35 hours thru stimated 600	th approx. the d itself. Apr pull tubing to 75°, Packer so 18/64 choke with H.	ree yards gravel il loth to May a wice due to hole t at 3292°. 5-1 th CP \$ and TP	L. 9 1h 12 -57 , 100.
Witnessed	enchor 3600° to 3610°. Sh Shot exploded on time and spent cleaning out. Was n re-caving. Two inch tubin Well flowed 76 bbls in 12 While cleaning out, gas es V. B. Peck by	America ST Nar Pos	the approx. the d itself. Apr pull tubing to 75°, Packer so 18/64 choke with N. n Glycerin Co. Company ereby swear or affirm the Distriction	ree yards gravel il loth to May a wice due to hole t at 3292'. 5-J th OP (and P)UP! [CA m that the information unlare	100.
Witnessed Subscribe	enchor 3600' to 5610'. Sh Shot exploded on time and spent cleaning out. Was m re-caving. Two inch tubin Well flowed 76 bbls in 12 While cleaning out, gas es 	America ST Nar Pos Rep	the approx. the d itself. Apr pull tubing to 75°, Packer so 18/64 choke with N. n Glycerin Co. Company ereby swear or affirm rue and correct, ne. Distri	ree yards gravel il loth to May a wice due to hole t at 3292'. 5-3 th GP \$ and P UP! [CA m that the informatio <i>unclane</i> ict Superintende y Oil Company	100. Shouler Title n given above

and the second • • • •

(1,1) = (1,2) + (1,1) + (1,1) + (1,2

E (S) • • • • · · ·

A second s

an an an tha far aga an an an an an

and a start of the st Start of the start of