State of New Mexico En , Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		w Mexi∞ 87503	WELL APL NO. 3002510486 5. Indicate Type of Lease STATE F 6. State Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PR DIFFERENT RESE	TICES AND REPORTS OF COPOSALS TO DRILL OR TO RVOIR. USE "APPLICATION 101) FOR SUCH PROPOSA	DEEPEN OR PLUG BACK TO A I FOR PERMIT*	7. Lease Name	or Unit Agreement Name
1. Type of Well: OIL GAS WELL A WELL	OTHER		J.V.	Baker
2. Name of Operator Yarbrough Oil L.P	•		8. Well No.	11
	NM 88231		9. Pool name or Bline	
4. Well Location Unit LetterE : 660	Feet From TheNort	Line and 16	550 Feet Fro	m The East
Section 27	Township 22	Range 37	NMPM	Lea
	10. Elevation (SAo	w whether DF, RKB, RT, GR, etc.)		
	•• •	dicate Nature of Notice,	_	
NOTICE OF INT			BSEQUENT I	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	IG OPNS.	PLUG AND ABANDON
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Open	oer 20 & 21 - 20	າດດ ່ ນ້ຳ		
1. Rigged by unit 2. Ran scraper at 3. Ran backer to 4. Ran CIP to 290 5. Halliburton pufrom 2905' to 6. Rigged down units.	tod bit to 2905' 2905', tested 05', tested to comped 260 sacks surface nit le marker, cut	to 500# 500# for 30 min. s class c cement	and circu	lated hole
1. Rigged the unit 2. Ran scraper an 3. Ran backer to 4. Ran CIP to 290 5. Halliburton pu from 2905' to 6. Rigged down un 7. Set 4" dry hol 8. Cleaned up loc Type or Print Name Paul Prais	and bit to 2905' 2905', tested 05', tested to amped 260 sacks surface nit le marker, cut cation	to 500# 500# for 30 min. s class c cement off dead men	and circu	DATE 10-21-0
1. Rigged the unit 2. Ran scraper at 3. Ran backer to 4. Ran CIP to 290 5. Halliburton pu from 2905' to 6. Rigged down un 7. Set 4" dry hol 8. Cleaned up loc	and bit to 2905' 2905', tested 05', tested to amped 260 sacks surface nit le marker, cut cation	to 500# 500# for 30 min. s class c cement off dead men	and circu	DATE 10-21-(

