

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

APR 24 11 43 AM '67

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)</small>		1a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. State Oil & Gas Lease No.
2. Name of Operator <b>ANADARKO PRODUCTION COMPANY</b>		6. Indicate Name <b>Langlie Mattix</b>
3. Address of Operator <b>P. O. Box 247, Hobbs, New Mexico 88240</b>		7. Farm or Lease Name <b>Penrose Sand Unit</b>
4. Location of Well UNIT LETTER <b>L</b> <b>1650</b> FEET FROM THE <b>South</b> LINE AND <b>990</b> FEET FROM THE <b>West</b> LINE, SECTION <b>28</b> TOWNSHIP <b>22S</b> RANGE <b>37E</b> N.M.P.M.		8. Well No. <b>4</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>N. A.</b>		10. Field and Pool, or Wildcat <b>Langlie Mattix</b>
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING CPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.		11. County <b>Lea</b>

1. Pull tubing and rods.
2. Cleanout through casing and shot hole to total depth.
3. Run Gamma Ray, Neutron, and Caliper surveys.
4. Close in well - awaiting further orders.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. J. Melton TITLE District Superintendent DATE 4/24/67

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: