

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

0+3-NMOCD-Hobbs 1-Foreman CRM
1-File 1-Laura Richardson-Midland
1-Engr. PJB 1-JA 1-BW

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection well	7. Unit Agreement Name
2. Name of Operator Getty Oil Company	8. Farm or Lease Name Skelly Penrose B Unit
3. Address of Operator P.O. Box 730, Hobbs, NM 88240	9. Well No. 10
4. Location of Well UNIT LETTER L, 1980 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 22S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Langlie Mattix
15. Elevation (Show whether DF, RT, GR, etc.) 3393' DF	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/19/82 TD 3999'. 5 1/2" csg @ 3999'. Perfs 3666-3727'. Rig up.
10/20/82 Pull tbq and pkr. Ran 4 3/4" bit tag fill 3691'. Clean out to 3732'. Pull bit.
10/21/82 Ran tbq and pkr. Set pkr @ 3549'. Knox treated 5 1/2" perfs 3666-3725 w/ 2000
gals 15% NE, 500# salt in 3 stages. Max 2700#, Min 1400#, rate 3 BPM. ISIP
1700#, 15 min 1350#. Flow back 84 BLW, 25 bbls prod. wtr.
10/22/82 Pull & lay down work string & pkr. Ran 5 1/2" Howco R-4 pkr, 114 jts, 3531',
2 3/8" cement lined tbq to 3541'. Displace hole w/ treated water. Set pkr
@3541'. Rig down move out.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D.R. CROCKETT TITLE Area Superintendent DATE October 25, 1982

ORIGINAL SIGNED BY

APPROVED BY JERRY SEXTON TITLE DATE NOV 1 1982

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 29 1982

G.C.D.
HOEES OFFICE