

Submit 3 Copies
to Appropriate
District Office

District I

P.O. Box 1980, Hobbs, NM 88240

District II

P.O. Drawer DD, Artesia, NM 88210

District III

1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

WELL API NO. 30 - 025 - 10536

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL ☒ GAS ☐
WELL ☒ WELL ☐ OTHER

2. Name of Operator
OXY USA INC.

3. Address of Operator
P.O. Box 50250 Midland, TX 79710

4. Well Location
Unit Letter I : 1,980 Feet From The SOUTH Line and 660 Feet From The EAST Line
Section 32 Township 22 S Range 37 E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3,369

7. Lease Name or Unit agreement Name

SKELLY PENROSE B UNIT

8. Well No.
7

9. Pool name or Wildcat
LANGLIE MATTIX 7 RVR Q-GB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3695' PBTD - 3690' PERFS - 3578' - 3676'

MIRU PU 5/26/93, NDWH, NUBOP, POOH W/ JUNK TBG. RIH & TAG @ 3594', CO TO 3690'. RIH W/ RBP SET @ 3501', ISOLATE CSG LEAK @ 407'-529', EST INJ RATE @ 1-1/4BPM @ 400#. MIX & PUMP 350SX CL C W/ 2% CACL2, SQZ TO 550#, WOC. RIH & TAG CMT @ 312', DO CMT TO 472', FELL FREE TO 1200', POOH. RIH & SPOT 10SX CMT ON TOP OF RBP @ 3501'. CIRC HOLE W/ MUD-LADEN FLUID, POOH TO 1550' & SPOT 25 SX (250') PLUG FROM 1550'-1300'. POOH, NDBOP, EIR 2BPM @ 450# & M&P 300SX CL C W/ 2% CACL2, SQZ TO 500#, TOC @ 214'. RDPU 6/9/93. SET 10SX SURFACE PLUG, POOH, REMOVE WH, INSTALL DRY HOLE MARKER. WELL P&A'D 6/10/93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 24 93

TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 14 1994

912

RECEIVED

JUN 25 1993

NO. 6088
- 110 -