

Submit 3 Copies
to Appropriate
District Office

District I
P.O. Box 1980, Hobbs, NM 88240
District II
P.O. Drawer DD, Artesia, NM 88210
District III
1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30 - 025 - 10546
1. Type of Well: OIL <input type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER INJECTION <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator OXY USA INC.		6. State Oil & Gas Lease No. B2320
3. Address of Operator P.O. Box 50250 Midland, TX 79710		7. Lease Name or Unit agreement Name SKELLY PENROSE B UNIT
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>990</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>22 S</u> Range <u>37 E</u> NMPM LEA County		8. Well No. 3
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3,363		9. Pool name or Wildcat LANGLIE MATTIX 7 RVR Q-GB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: TEMPORARILY ABANDON ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3800' PBTD - 3740' PERFS - 3594' - 3709'

MIRU PU 5/12/93, 5-1/2" CSG IS COLLAPSED INSIDE 8-5/8"X5-1/2"WH. REMOVE 5-1/2" WH & CSG STUB. POOH W/ TBG RIH W/ RBP, RUN STRING SHOT & POOH W/ 42' 5-1/2" CSG. RIH W/ 1 JT 5-1/2" CSG, SET SLIPS, CUT CSG, WELD ON BELL NIPPLE, NUBOP, TEST CSG TO 500# - HELD OK, REL RBP, RIH & TAG @ 3655', TEST CSG TO 500# - HELD OK, POOH W/ PKR & TBG. RIH W/ CIBP & SET @ 3541', CIRCULATE HOLE W/ CORR INHIB, POOH W/ TBG, NDBOP, NUWH, TEST CSG TO 750# - 30MIN - HELD OK, RDPU 5/17/93. WELL IS TA'D.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 09 93
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 15 1993

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary
Abandonment Expires 6-1-98

JUN 14 1993

LCD HOBBS OFFICE